



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM TDCI
Colour	Silver
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-05-26
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-16
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	29
Total items failed	14

MOT #18	2023-05-17 15:05
MOT test number	997794336764
Result	✓ Passed
Next expiry date	2024-05-16
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #17	2023-05-17 09:37
MOT test number	307525627388
Result	✗ Failed
Fail	Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Minor	Nearside Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #162022-04-13 15:54

MOT test number640419453169

Result

✓ Passed

- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Offside Front seat base worn but secure
- Advice

Play in steering rack inner joint(s)

**MOT #15**

2022-04-13 08:37

MOT test number

703338898801

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front seat base worn but secure
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Play in steering rack inner joint(s)
- Fail** Emissions not tested due to exhaust condition (8.2.2.2 (e))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))

MOT #14

2021-04-22 12:51

MOT test number

603272694902

Result**✓ Passed**

**MOT #13** 2021-04-19 10:17**MOT test number** 420453229977**Result** ✗ Failed

Fail Nearside Rear Suspension arm pin or bush excessively worn Trailing arm front pivoting bush has broken its bondings (5.3.4 (a) (i))

Fail Offside Rear Suspension arm pin or bush excessively worn Trailing arm front pivoting bush has broken its bondings (5.3.4 (a) (i))

MOT #12 2020-05-01 09:51**MOT test number** 973690226475**Result** ✓ Passed**MOT #11** 2019-04-04 15:36**MOT test number** 601131618188**Result** ✓ Passed

Advice Rear N\s and O\s Trailing arm front pivoting bushes are starting to break their bonding's.

Advice Chip in windscreen in Zone "B" not greater than 40mm

MOT #10 2018-04-03 10:32**MOT test number** 825326683663**Result** ✓ Passed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9 2018-04-03 10:32**MOT test number** 508320754125**Result** ✗ Failed

Pass with rectification Nearside Front Front position lamp(s) not working (1.1.A.3b)

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Pass with rectification Offside Front Front position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)

**MOT #8** 2017-04-06 15:39**MOT test number** 405621319371**Result** ✓ Passed**Advice** Front n\s and o\s tyre inner walls are starting to crack badly**MOT #7** 2017-04-06 09:28**MOT test number** 581373033742**Result** ✗ Failed**Fail** Nearside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement front pivoting bush (2.4.G.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement front pivoting bush starting to break its bonding (2.4.G.2)**Advice** Front n\s and o\s tyre inner walls are starting to crack badly**MOT #6** 2016-03-29 16:02**MOT test number** 394304576456**Result** ✓ Passed**MOT #5** 2016-03-29 09:02**MOT test number** 331875195899**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #4** 2015-03-31 10:33**MOT test number** 817610995006**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #3** 2014-04-02 15:28**MOT test number** 176952694421**Result** ✓ Passed



MOT #2	2013-04-08 16:43
MOT test number	619758993009
Result	✓ Passed

MOT #1	2012-03-28 12:12
MOT test number	266768282003
Result	✓ Passed

- Notice** Advise os/f driving light bottom cracked filling up with water,
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Centre Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
16 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	16 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	BV09KHE
Plate since	2019-03-29
Current registration	BV09KHE
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-04-06
Last registration	2023-05-17
Complete history	See info



Registration #1	2009-04-06	28 mi
Registration #2	2012-03-28	79.560 mi
Registration #3	2013-04-08	108.219 mi
Registration #4	2014-04-02	112.083 mi
Registration #5	2015-03-31	115.458 mi
Registration #6	2016-03-29	118.942 mi
Registration #7	2016-03-29	118.942 mi
Registration #8	2017-04-06	122.693 mi
Registration #9	2017-04-06	122.693 mi
Registration #10	2018-04-03	126.754 mi
Registration #11	2019-05-20	131.377 mi
Registration #12	2019-05-20	131.377 mi
Registration #13	2019-05-20	131.377 mi
Registration #14	2019-05-20	131.377 mi
Registration #15	2019-05-20	131.377 mi
Registration #16	2019-05-20	131.377 mi
Registration #17	2019-05-20	131.377 mi
Registration #18	2019-05-20	131.377 mi
Registration #19	2019-05-20	131.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1943 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9G39426