





report date: 2024-03-28

General information

Make	NISSAN
Model	PATHFINDER DCI AVENTURA
Colour	Blue
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 сс
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	33.2 mpg
Consumption combined	28.8 mpg
CO2 emission	264 g/km
CO2 label	М



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date	2021-09-13
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history	M	OT	history
-------------	---	----	---------

MOT expiry date	2024-06-04
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	28
Total items failed	11

MOT #20		2023-06-05 13:06
MOT test	number	439446622899
Result		✓ Passed
Next expi	ry date	2024-06-04
Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #19	2022-08-29 13:39
MOT test number	494627174000
Result	✓ Passed

MOT #18		2021-10-02 09:03
MOT test	number	483661055709
Result		✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (i))	Vehicle structure is corroded but structural rigidity is not significantly reduced c	hassis (6.1.1 (c)

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #17 2021-09-29 10:57 **MOT** test number 859707764218 Result × Failed **Advice** Rear Tyre worn close to legal limit/worn on edge Both (5.2.3 (e)) **MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) **MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced chassis (6.1.1 (c) (i)) **MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT test number
710661691667

Result

Advice Offside Front Lower Suspension arm ball joint has slight play Slight lift (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm ball joint has slight play Slight Lift (5.3.4 (a) (i))

Minor (b) (i))

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

MOT #15

MOT test number

682281284951

Result

Advice

Offside Front Lower Suspension arm ball joint has slight play Slight lift (5.3.4 (a) (i))

Minor

(b) (i))

Advice

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Front Lower Suspension arm ball joint has slight play Slight Lift (5.3.4 (a) (i))

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #14 2019-09-30 12:03

MOT test number 231079215628

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

MOT #13 2018-08-15 09:35

MOT test number 695512811545

Result
✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Lower Ball joint slight lift

Advice Nearside Front Lower Ball joint slight lift

MOT #12 2018-08-14 12:18

MOT test number 416359973773

Result X Failed

Advice Offside Front Lower Ball joint slight lift

MAJOR Electronic stability control warning lamp indicates a fault (7.12 (e))

DANGEROUS Stop lamp(s) all not working (4.3.1 (a) (iii))

Advice Nearside Front Lower Ball joint slight lift

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

MOT #11 2017-08-04 08:11

MOT test number 896837154616

Result ✓ Passed

CarCheck.co.uk page 5/13



MOT test number

FG07UMM

report date: 2024-03-28

837084105624

MOT test number

Result

Pass with rectification

Offside Headlamp aim too high (1.8)

Pass with rectification

Nearside Headlamp aim too high (1.8)

Fail

Offside Rear fog lamp not working (1.3.2b)

MOT #9

MOT test number

Result

MOT #8

2016-06-27 14:32

224705774242

✓ Passed

Result

Passed

Result \(\sqrt{Passed}\)

MOT #7 2015-08-25 11:25

MOT test number 431466233466

Result X Failed

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Fail Offside Rear Stop lamp not working (1.2.1b)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Headlamp not working on dipped beam (1.7.5a)

Fail Offside Rear fog lamp not working (1.3.2b)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT #6	2014-08-21 17:33
MOT test number	119663734224
Result	✓ Passed
MOT #5	2014-04-22 13:54
MOT test number	348562614160
Result	✓ Passed
MOT #4	2013-08-16 14:31
MOT test number	515768223218
Result	✓ Passed
MOT #3	2012-03-30 09:14
MOT test number	927950292065
Result	✓ Passed
Notice Front pads may be wearing thin	
Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
MOT #2	2011-04-06 12:09
MOT test number	767856691056

MOT #2	2011-04-06 12:09
MOT test number	767856691056
Result	✓ Passed
MOT #1	2010-04-06 13:10
MOT test number	204006490025
Result	✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-04-11
Last registration	2023-06-05
Complete history	See info



2007-04-11	12 mi
2010-04-06	18.397 mi
2011-04-06	41.488 mi
2012-03-30	50.635 mi
2013-08-16	52.355 mi
2014-04-22	52.884 mi
2014-08-21	56.158 mi
2015-08-25	65.912 mi
2015-08-27	65.912 mi
2016-06-27	76.221 mi
2017-08-03	92.509 mi
	71.777 es
	9.777 es
	11.777 es
	91.777 esi
	11.777 es
	9.777 es
	11.777 es
	9.777 es
	11.777 es
	11.777 es
	71,777 es
	2010-04-06 2011-04-06 2012-03-30 2013-08-16 2014-04-22 2014-08-21 2015-08-25 2015-08-27 2016-06-27 2017-08-03

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1763 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2208 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1

Number of axles2Engine number865510