




report date: 2024-09-06

General information

|                     |                      |
|---------------------|----------------------|
| Make                | JAGUAR               |
| Model               | XF V6 PREMIUM LUXURY |
| Colour              | Black                |
| Year of manufacture | 2008                 |
| Top speed           | 143 mph              |
| Gearbox             | 6 speed automatic    |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 204 BHP             |
| Max. torque             | 435 Nm at 1.900 rpm |
| Engine capacity         | 2.720 cc            |
| Cylinders               | 6                   |
| Fuel type               | Diesel              |
| Consumption city        | 27.2 mpg            |
| Consumption extra urban | 48.7 mpg            |
| Consumption combined    | 37.7 mpg            |
| CO2 emission            | 199 g/km            |
| CO2 label               | J                   |





MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-03-15 |
| MOT pass rate      | 81 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 3          |
| Total advice items | 26         |
| Total items failed | 5          |

MOT #16 2024-03-13 10:09

MOT test number 163759268607

Result ✔ Passed

Next expiry date 2025-03-15

- Advice** Rear rear subframe getting corroded
- Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges worn (5.2.3 (e))
- Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Rear Inner Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #15 2023-03-13 13:41

MOT test number 553038584104

Result ✔ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))
- Advice** Undertrays fitted
- Advice** Oil leak, but not excessive At the Deaf (8.4.1 (a) (i))



|                        |                  |
|------------------------|------------------|
| <b>MOT #14</b>         | 2022-03-16 15:25 |
| <b>MOT test number</b> | 387934290508     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #13</b>         | 2021-03-11 13:52 |
| <b>MOT test number</b> | 332421124286     |
| <b>Result</b>          | ✓ Passed         |

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Oil leak, but not excessive axle (8.4.1 (a) (i))
- Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

|                        |                  |
|------------------------|------------------|
| <b>MOT #12</b>         | 2020-03-14 13:10 |
| <b>MOT test number</b> | 218152275346     |
| <b>Result</b>          | ✓ Passed         |

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Inner Tyre slightly damaged side wall (5.2.3 (d) (ii))
- Advice** Rear Oil leak, but not excessive diff (8.4.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



|                        |  |
|------------------------|--|
| <b>MOT #11</b>         | 2019-01-11 15:00   |
| <b>MOT test number</b> | 221987797400   |
| <b>Result</b>          | ✓ Passed   |
| <b>Advice</b>          | Dampness around rear diff  |
| <b>Minor</b>           | Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| <b>Advice</b>          | Nsr top inner bushes have slight free play   |
| <b>Advice</b>          | Nsf tyre worn outer  |

|                        |                  |
|------------------------|------------------|
| <b>MOT #10</b>         | 2018-01-17 10:33 |
| <b>MOT test number</b> | 910337999828     |
| <b>Result</b>          | ✓ Passed         |

|                        |   |
|------------------------|---|
| <b>MOT #9</b>          | 2018-01-10 08:43  |
| <b>MOT test number</b> | 671246939674  |
| <b>Result</b>          | ✗ Failed  |
| <b>Fail</b>            | Rear registration plate character(s) incorrectly spaced (6.3.4a)  |
| <b>Fail</b>            | Front registration plate character(s) incorrectly spaced (6.3.4a) |
| <b>Fail</b>            | Offside Front Headlamp not working on main beam (1.7.5a)          |

|                        |                  |
|------------------------|------------------|
| <b>MOT #8</b>          | 2017-01-18 12:11 |
| <b>MOT test number</b> | 258109195297     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #7</b>          | 2016-01-06 17:15 |
| <b>MOT test number</b> | 735668196542     |
| <b>Result</b>          | ✓ Passed         |



**MOT #6** 2014-12-16 13:04

**MOT test number** 247850354363

**Result** ✓ Passed

**MOT #5** 2013-12-24 10:48

**MOT test number** 938648353302

**Result** ✓ Passed

**Advice** Offside Front Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #4** 2013-12-24 10:48

**MOT test number** 225678953324

**Result** ✗ Failed

**Pass with rectification** Offside Front Wheel nut(s) missing (4.2.A.1e)

**Advice** Offside Front Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #3** 2012-12-03 17:40

**MOT test number** 457088732400

**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #2** 2011-06-17 10:37

**MOT test number** 829258361176

**Result** ✓ Passed

**MOT #1** 2011-06-17 10:37

**MOT test number** 285958561427

**Result** ✗ Failed

**Pass with rectification** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 September 2025

✓  
**MOT**

**Expires:**  
15 March 2025

**Tax status** Valid until 1 September

**Days left** 347

**MOT expiry date** 15 March 2025

**Full MOT history** [See MOT history](#)

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | J          |
| <b>Single payment (12 months)</b>              | £ 365,00,- |
| <b>Single six month payment</b>                | £ 200,75,- |
| <b>Total payable by 12 monthly instalments</b> | £ 383,25,- |




Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.


Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                                    |          |
|------------------------------------|----------|
| <b>Trade retail value</b>          | £ 19,999 |
| <b>Auction value</b>               | £ 19,999 |
| <b>Average private trade value</b> | £ 19,999 |

**More info** >





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |     |
|-------|-------|-----|
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-09-06    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-09-06    |

More info >



**Finance check**

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


|                          |          |
|--------------------------|----------|
| <b>Finance company</b>   | REDACTED |
| <b>Date of agreement</b> | REDACTED |
| <b>Agreement type</b>    | REDACTED |
| <b>Agreement term</b>    | REDACTED |
| <b>Agreement number</b>  | REDACTED |
| <b>Contact info</b>      | REDACTED |

**More info** >



Mileage check

|                                   |                          |
|-----------------------------------|--------------------------|
| <b>Odometer</b>                   | In miles                 |
| <b>Mileage registrations</b>      | 15                       |
| <b>First mileage registration</b> | 2008-04-14               |
| <b>Last registration</b>          | 2024-03-13               |
| <b>Complete history</b>           | <a href="#">See info</a> |



|                         |            |            |
|-------------------------|------------|------------|
| <b>Registration #1</b>  | 2008-04-14 | 21 mi      |
| <b>Registration #2</b>  | 2011-06-17 | 53.739 mi  |
| <b>Registration #3</b>  | 2012-12-03 | 71.881 mi  |
| <b>Registration #4</b>  | 2013-12-24 | 83.024 mi  |
| <b>Registration #5</b>  | 2014-12-16 | 93.473 mi  |
| <b>Registration #6</b>  | 2016-01-06 | 105.296 mi |
| <b>Registration #7</b>  | 2017-01-18 | 115.138 mi |
| <b>Registration #8</b>  | 2018-01-10 | 125.918 mi |
| <b>Registration #9</b>  | 2019-01-01 | 135.000 mi |
| <b>Registration #10</b> | 2020-01-01 | 145.000 mi |
| <b>Registration #11</b> | 2021-01-01 | 155.000 mi |
| <b>Registration #12</b> | 2022-01-01 | 165.000 mi |
| <b>Registration #13</b> | 2023-01-01 | 175.000 mi |
| <b>Registration #14</b> | 2024-01-01 | 185.000 mi |
| <b>Registration #15</b> | 2024-03-13 | 195.000 mi |

[More info >](#)



## Safety ratings

**NCAP rating** ★★★★★

**Video** [see crash video](#)



## Dimensions & weight

|                            |         |
|----------------------------|---------|
| <b>Width</b>               | 2053 mm |
| <b>Height</b>              | 1460 mm |
| <b>Length</b>              | 4961 mm |
| <b>Wheel base</b>          | 2909 mm |
| <b>Kerb weight</b>         | 1829 kg |
| <b>Max. allowed weight</b> | 2310 kg |

## Additional information

|                           |                  |
|---------------------------|------------------|
| <b>Fuel tank capacity</b> | 69 l             |
| <b>Fuel delivery</b>      | Direct Injection |
| <b>Number of doors</b>    | 4                |
| <b>Number of seats</b>    | 5                |
| <b>Number of axles</b>    | 2                |
| <b>Engine number</b>      | 03027317G        |