





report date: 2024-03-28

General information

Make	BMW
Model	740 740D M SPORT
Colour	Black
Year of manufacture	2010
Top speed	155 mph
0 - 60 mph	6.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	302 BHP
Max. torque	600 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	181 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2022-02-03


Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-03-13
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	6
Total items failed	5

MOT #16	2024-03-09 11:06
MOT test number	623670340852
Result	✓ Passed
Next expiry date	2025-03-13
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front suspension arm front bush slight (5.3.4 (a) (i))	

MOT #15	2023-03-04 11:18
MOT test number	243962780591
Result	✓ Passed
MOT #14	2022-03-14 12:18
MOT test number	882534499260
Result	✓ Passed
MOT #13	2021-07-08 13:34
MOT test number	853988273535
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2021-07-07 13:26

MOT test number 193494232076

Result X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge badly worn on inner edge (5.2.3 (e))

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure inner side wall (5.2.3 (d) (ii))

MOT #11 2020-07-13 15:13

MOT test number 196778937632

Result \(\sqrt{Passed} \)

MOT #10 2019-05-22 14:46

MOT test number 660843690855

MOT #9 2018-05-22 11:50

MOT test number 746036863618

Result ✓ Passed

MOT #8 2017-05-25 09:55

MOT test number 258233444577

Advice Nearside Rear Tyre worn close to the legal limit WORN ON INSIDE - 275/35R20 102Y (4.1.E.1)

Advice GOODYEAR EXCELLENCE B RUN-FLAT ALROUND

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7 2017-05-19 15:40

MOT test number 158958292809

Result × Failed

Advice Nearside Rear Tyre worn close to the legal limit WORN ON INSIDE - 275/35R20 102Y (4.1.E.1)

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure 245/40R20 99Y (4.1.D.1b)

Advice GOODYEAR EXCELLENCE B RUN-FLAT ALROUND

MOT #6 2016-01-06 14:34

MOT test number 950700095919

Result
✓ Passed

MOT #5 2015-05-28 10:43

MOT test number 155028245125

Result ✓ Passed

MOT #4 2014-06-20 11:05

MOT test number 187891574112

Result

Passed

MOT #3 2014-06-20 09:29

MOT test number 418591674106

Result X Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2 2013-11-14 11:20

MOT test number 689368113351

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1

MOT test number

425797813499

Result

Fail Offside Rear Road wheel cracked (4.2.A.1a)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

,		
For how long did the current and previous owner(s) have this BMW? How many owners defined the current and see all owner registrations. Download the full report		ve?

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	NIN CONTRACTOR	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #18

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-01
Last registration	2024-03-09
Complete history	See info



Registration #1	2010-09-01	9 mi
Registration #2	2013-11-13	26.166 mi
Registration #3	2013-11-14	26.171 mi
Registration #4	2014-06-20	28.546 mi
Registration #5	2014-06-20	28.551 mi
Registration #6	2015-05-28	40.701 mi
Registration #7	2016-01-06	42.557 mi
Registration #8	2017-05-19	60.106 mi
Registration #9	2017-05-25	60.212 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		0.00 44
Registration #15		11.777 mi
Registration #16		0.00 44
Registration #17		0.074

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1902 mm
Height	1488 mm
Length	5072 mm
Wheel base	3210 mm
Kerb weight	1950 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	80 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles2Engine number25827519