





report date: 2024-03-28

General information

Make	AUDI
Model	A4 TDI DPF S LINE
Colour	Black
Year of manufacture	2010
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-23

Pictures 38

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-01
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	29
Total items failed	5

MOT #16	2023-06-02 14:29
MOT test number	155992771211
Result	✓ Passed
Next expiry date	2024-06-01

MOT #15		2023-06-02 14:29
MOT test number		941801496943
Result		X Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))	

CarCheck.co.uk page 3/14



Fail

BG10BVM

report date: 2024-03-28

MOT #14 2022-04-25 16:22 **MOT** test number 529380025932 Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e)) Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

 MOT #13
 2022-04-25 15:19

 MOT test number
 484266492160

 Result
 ★ Failed

Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice **Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Front Service brake excessively fluctuating (1.2.1 (e)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice

CarCheck.co.uk page 4/14

Nearside Front Service brake excessively fluctuating (1.2.1 (e))



report date: 2024-03-28

MOT #12

MOT test number

134112130413

Result

Advice Covers fitted

MOT test number

712465578294

Result

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10

MOT test number

Result

MOT #9

MOT test number

2018-11-21 13:30

MOT test number

360514974553

Result

Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT test number

Result

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #7 2017-11-21 15:14

MOT test number 776719976810

Result \rightarrow Passed

MOT #6 2017-11-21 15:14

MOT test number 330621604698

Result × Failed

Pass with rectification Nearside Headlamp aim too low (1.8)

MOT #5 2016-11-23 10:04

MOT test number 227607791803

Result \rightarrow Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2015-11-20 10:38

MOT test number 540277349872

MOT #3 2014-11-18 11:38

MOT test number 915002324376

Result \(\sqrt{Passed} \)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #2 2013-11-22 11:24

MOT test number 415436823402

Result ✓ Passed

Notice Headlight washers don't go back into bumper once operated

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #1 2013-05-23 18:29

MOT test number 229223843469

Result ✓ Passed

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



MOT

Expires:
1 June 2024

Tax status

Days left

MOT expiry date

Full MOT history

Expired at 30 September

211 days too late

1 June 2024

See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

BG10BVM

report date: 2024-03-28

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

Plate changes

More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-27
Last registration	2023-06-02
Complete history	See info



Registration #1	2010-05-27	19 mi
Registration #2	2013-05-23	39.798 mi
Registration #3	2013-11-22	40.152 mi
Registration #4	2014-11-18	50.696 mi
Registration #5	2015-11-20	60.032 mi
Registration #6	2016-11-23	64.108 mi
Registration #7	2017-11-21	67.940 mi
Registration #8	2017-11-21	67.940 mi
Registration #9	2018-11-21	70.801 mi
Registration #10		11.117 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

CarCheck.co.uk page 13/14



BG10BVM report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1854 mm
Height	1372 mm
Length	4625 mm
Wheel base	2751 mm
Kerb weight	1470 kg
Max. allowed weight	1975 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 14/14

Number of axles 2

Engine number CAH 129958