



AD59TYG

report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ECONETIC TDCI
Colour	Silver
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg





Internet history

Entry 2

Date	2021-08-07
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-17
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT #18	2023-09-09 16:28
MOT test number	994827726655
Result	✓ Passed
Next expiry date	2024-09-08

MOT #17	2022-09-03 09:05
MOT test number	964471844807
Result	✓ Passed

MOT #16	2022-09-01 11:25
MOT test number	840700276921
Result	✗ Failed

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #15	2021-07-17 09:39
MOT test number	824240415840
Result	✓ Passed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14**

2020-09-03 08:21

MOT test number

865317798943

Result

✓ Passed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement arm (5.3.4 (a) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement arm (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13

2020-09-03 08:21

MOT test number

667088375822

Result

✗ Failed

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement arm (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement arm (5.3.4 (a) (i))

MOT #12

2019-10-01 16:49

MOT test number

576498730120

Result

✓ Passed

MOT #11

2019-10-01 08:29

MOT test number

373109754647

Result

✗ Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #10** 2018-09-07 12:24**MOT test number** 389486977272**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2017-09-15 14:25**MOT test number** 508716092923**Result** ✓ Passed**Advice** Offside Front Inner Steering system has slight free play detected at steering wheel rackend (2.2.A.1b)**MOT #8** 2017-09-15 08:16**MOT test number** 678182549664**Result** ✗ Failed**Advice** Offside Front Inner Steering system has slight free play detected at steering wheel rackend (2.2.A.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2016-08-19 16:12**MOT test number** 508183328174**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #6**

2016-08-19 08:31

MOT test number

269531655701

Result

✗ Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Suspension arm rubber bush bonding deteriorated resulting in excessive movement sat bush (2.4.G.2)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Headlamp aim too high (1.8)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 215/55/16 (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front registration plate deteriorated (6.3.1d)**Fail** Offside Rear Suspension arm rubber bush bonding deteriorated resulting in excessive movement sat bush (2.4.G.2)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Headlamp insecure (1.7.3)**MOT #5**

2015-09-17 15:41

MOT test number

341948028555

Result

✓ Passed

MOT #4

2014-09-01 15:23

MOT test number

649574144271

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3**

2013-09-17 15:29

MOT test number

945850863257

Result

✓ Passed



MOT #2	2012-09-03 09:45
MOT test number	207847942265
Result	✓ Passed

MOT #1	2012-09-03 09:45
MOT test number	319167342453
Result	✗ Failed
<div>Pass with rectification</div> Offside Rear Stop lamp not working (1.2.1b)	



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-12-18
Last registration	2023-09-09
Complete history	See info



Registration #1	2009-12-18	6 mi
Registration #2	2012-09-03	96.682 mi
Registration #3	2013-09-17	103.899 mi
Registration #4	2015-09-17	122.617 mi
Registration #5	2016-08-19	133.468 mi
Registration #6	2016-08-19	133.469 mi
Registration #7	2017-09-15	178.559 mi
Registration #8	2017-09-15	178.559 mi
Registration #9	2018-09-07	164.208 mi
Registration #10	2019-10-01	180.958 mi
Registration #11	2019-10-01	180.958 mi
Registration #12	2019-10-01	180.958 mi
Registration #13	2019-10-01	180.958 mi
Registration #14	2019-10-01	180.958 mi
Registration #15	2019-10-01	180.958 mi
Registration #16	2019-10-01	180.958 mi
Registration #17	2019-10-01	180.958 mi
Registration #18	2019-10-01	180.958 mi
Registration #19	2019-10-01	180.958 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1559 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9D07771