



General information

Make	LAND ROVER
Model	FREELANDER TD4 HSE
Colour	Silver
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	158 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-21
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	28
Total items failed	14

MOT #12	2024-03-22 16:56
MOT test number	957521094468
Result	✓ Passed
Next expiry date	2025-03-21

MOT #11	2023-03-10 14:27
MOT test number	320878183068
Result	✓ Passed
Advice	General corrosion
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2022-03-10 11:34
MOT test number	499288488884
Result	✓ Passed

MOT #9	2021-02-22 11:20
MOT test number	647127021390
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2020-02-26 11:04**MOT test number** 884568012813**Result** ✓ Passed**Advice** Rear brake discs are worn**MOT #7** 2020-02-26 09:46**MOT test number** 157177911856**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear brake discs are worn**MOT #6** 2019-02-25 08:40**MOT test number** 307143108407**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** General corrosion under vehicle.

**MOT #5**

2019-02-22 09:21

MOT test number

327661592155

Result**✗ Failed**

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Tyre has radial cracking
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Advice** General corrosion under vehicle.
- Fail** Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front wiper slightly smearing the windscreen
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a))
- Advice** Offside Front Tyre wearing on inner & outer treads
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear wiper not cleaning screen

**MOT #4** 2018-03-07 10:19**MOT test number** 213283450493**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Tyre has a cut on outer side wall but no cords exposed.

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3 2018-03-07 10:19**MOT test number** 647616393201**Result** ✗ Failed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Pass with rectification Offside Front Headlamp aim too high (1.8)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Tyre has a cut on outer side wall but no cords exposed.

Pass with rectification Nearside Front Headlamp aim too low (1.8)

MOT #2 2017-03-21 14:47**MOT test number** 593097636699**Result** ✓ Passed**MOT #1** 2017-03-20 15:06**MOT test number** 408178440200**Result** ✗ Failed

Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)

Advice Front Brake pad(s) wearing thin both (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
21 March 2025

Tax status	Valid until 1 November
Days left	185
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-09-24
Last registration	2024-03-22
Complete history	See info



Registration #1	2007-09-24	23 mi
Registration #2	2017-03-20	37.032 mi
Registration #3	2017-03-21	37.032 mi
Registration #4	2018-03-07	54.857 mi
Registration #5	2018-03-07	54.857 mi
Registration #6	2019-02-22	72.943 mi
Registration #7	2019-02-25	72.943 mi
Registration #8	2019-03-20	91.277 mi
Registration #9	2019-03-20	91.277 mi
Registration #10	2019-03-20	91.277 mi
Registration #11	2019-03-20	91.277 mi
Registration #12	2019-03-20	91.277 mi
Registration #13	2019-03-20	91.277 mi
Registration #14	2019-03-20	91.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2180 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1770 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ594013576224DT