





report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ROLAND GARROS 16V
Colour	Black
Year of manufacture	2003
Top speed	123 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	153 g/km
CO2 label	G



CarCheck.co.uk page 1/13



MOT history

MOT expiry date	2021-10-14
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	25
Total items failed	15

MOT #20	2020-10-15 14:55
MOT test number	102855061820
Result	✓ Passed
Next expiry date	2021-10-14
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #19		2019-10-11 12:07
MOT test	number	772076731633
Result		✓ Passed
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/13



LL03PZP

report date: 2024-03-28

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #17
 2017-10-14 07:43

 MOT test number
 665242508097

 Result
 ✓ Passed

 MOT #16
 2016-11-09 10:27

 MOT test number
 376599160260

 Result
 ✓ Passed

 Advice
 Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #15

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

 MOT #14
 2015-11-17 15:37

 MOT test number
 283549142109

 Result
 ✓ Passed

CarCheck.co.uk page 3/13



MOT #13 2014-10-27 12:42

MOT test number 358380704361

Result ✓ Passed

Notice Fuel tank support strap corroded

Notice Off side front tyre worn on the inner edge

MOT #12 2014-10-24 14:38

MOT test number 978617994228

Result X Failed

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Notice Fuel tank support strap corroded

Fail Nearside Rear Seat belt insecurely fixed to the vehicles structure (5.2.1a)

Notice Off side front tyre worn on the inner edge

MOT #11 2013-11-01 16:40

MOT test number 277075003386

Result
✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Tread lifting on the off side rear tyre

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #10 2012-10-16 10:46

MOT test number 387870792418

Result \(\sqrt{Passed} \)

MOT #9 2011-10-19 12:06

MOT test number 926662491249

CarCheck.co.uk page 4/13



MOT #8 2011-10-19 09:47

MOT test number 228012991240

Result X Failed

Fail Offside Front Windscreen wiper blade insecure (8.2.2)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Rear Registration plate lamp not working (1.1.C.1d)

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)

MOT #7 2010-08-07 09:49

MOT test number 390109510206

Result
✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

MOT #6 2009-08-07 11:52

MOT test number 603709919286

Result ★ Failed

Pass with rectification Offside Front Headlamp not in good working order adversely affecting beam image (1.2.4a)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Pass with rectification Offside Side repeater incorrect colour (1.4.A.2f)

MOT #5 2009-08-07 11:52

MOT test number 451209919277

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #4 2008-08-08 14:29

MOT test number 844021328253

Result ✓ Passed

CarCheck.co.uk page 5/13



LL03PZP

report date: 2024-03-28

MOT #3 2008-08-08 11:58 570541128254 **MOT** test number Result × Failed Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Offside Front Headlamp not working on dipped beam (1.7.5a) Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Front brake disc in such a condition that it is seriously weakened (3.5.1i) Fail Fail Nearside Front Headlamp not working on dipped beam (1.7.5a) Fail Offside Front Side repeater incorrect colour (1.4.A.2f)

MOT test number

962692227292

Result

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #1	2006-07-25 13:00
MOT test number	153996006201
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check

Tax expired: 1 March 2021



X MOT

Expired: 14 October 2021

Tax status	Expired at 1 March 2021
Days left	1154 days too late
MOT expiry date	14 October 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when miscory		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		EOT
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK OK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-08-07
Last registration	2020-10-15
Complete history	See info



Registration #1	2003-08-07	13 mi
Registration #2	2006-07-25	21.166 mi
Registration #3	2007-08-10	28.174 mi
Registration #4	2008-08-08	34.230 mi
Registration #5	2008-08-08	34.230 mi
Registration #6	2009-08-07	39.173 mi
Registration #7	2010-08-07	48.492 mi
Registration #8	2011-10-19	58.585 mi
Registration #9	2011-10-19	58.585 mi
Registration #10	2012-10-16	67.929 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		91.777 esi
Registration #16		11.777 es
Registration #17		91.777 esi
Registration #18		11.777 es
Registration #19		11.777 es
Devictor #20		
Registration #20		

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionin
50295	
50482	
50501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1652 mm
Height	1432 mm
Length	3835 mm
Wheel base	2445 mm
Kerb weight	1025 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	FX3V1810523 page 13/13