



report date: 2024-03-28

General information

Make	FIAT
Model	500X T-JET EASY PLUS
Colour	Grey
Year of manufacture	2017
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	214 Nm at 2.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-21
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-14
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	18
Total items failed	0

MOT #8	2024-01-15 15:14
MOT test number	714475984241
Result	✓ Passed
Next expiry date	2025-01-14

MOT #7	2024-01-10 17:07
MOT test number	459885176144
Result	✗ Failed
<b>MAJOR</b> Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))	

**MOT #6**

2023-12-08 15:47

**MOT test number**

285601007780

**Result****✗ Failed****MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Front Exhaust has a minor leak of exhaust gases flexi deteriorated (6.1.2 (a))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall (5.2.3 (d) (i))**Advice** Offside Front tyre fitted inside facing out**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Rear Suspension component damaged but not seriously weakened both rear shock absorber dust covers split (5.3.3 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear parking brake has low recorded effort at wheel**MOT #5**

2023-04-28 14:19

**MOT test number**

902330985412

**Result****✓ Passed****Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front exhaust flexi deteriorated**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Rear Suspension component damaged but not seriously weakened shock absorber dust cover split (5.3.3 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))



MOT #4	2022-03-10 08:43
MOT test number	487265093204
Result	✓ Passed
MOT #3	2021-02-20 11:14
MOT test number	377779277923
Result	✓ Passed
MOT #2	2021-02-20 11:07
MOT test number	198165536666
Result	✗ Failed
MAJOR Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
MOT #1	2020-02-10 13:16
MOT test number	862661940705
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
12 February 2024

✓

MOT

Expires:  
14 January 2025

Tax status	Expired at 12 February 2024
Days left	76 days too late
MOT expiry date	14 January 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-03-01
Last registration	2024-01-15
Complete history	<a href="#">See info</a>



Registration #1	2017-03-01	18 mi
Registration #2	2020-02-10	26.960 mi
Registration #3	2021-02-20	35.920 mi
Registration #4	2021-02-20	35.920 mi
Registration #5	2022-05-20	35.920 mi
Registration #6	2022-05-20	35.920 mi
Registration #7	2022-05-20	35.920 mi
Registration #8	2022-05-20	35.920 mi
Registration #9	2022-05-20	35.920 mi
Registration #10	2022-05-20	35.920 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1350 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2148185