





report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO L1H1 2700 SPORTIVE CDTI BITURBO S/S
Colour	Blue
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-11-03

Pictures 21

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-10-15	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

CarCheck.co.uk page 2/11



WH17HEU report date: 2024-03-29

MOT history

MOT expiry date	2024-12-20
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #6	2023-12-19 09:20
MOT test number	564348661317
Result	✓ Passed
Next expiry date	2024-12-20
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5		2022-12-16 09:12
MOT test nui	mber	203799940852
Result		✓ Passed
Advice W	ashers suspect frozen(further investigation advisable)	
Advice R	ear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice St	tonechip in windscreen	

MOT #4	2021-12-21 16:40
MOT test number	495109759249
Result	✓ Passed
Advice Nearside Rear Nail in tyre 3.5mm	

MOT #3	2021-03-29 15:51
MOT test number	736802218917
Result	✓ Passed

CarCheck.co.uk page 3/11



VH17HEU

report date: 2024-03-29

Passed

MOT #2 2021-03-29 07:31

568371116761 **MOT** test number

Result × Failed

MAJOR Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Front Brake hose excessively damaged (1.1.12 (b) (ii))

MAJOR Front Inner Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #1 2020-03-14 11:40

MOT test number 412312856262

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



WH17HEU report date: 2024-03-29

Tax & MOT check



✓ MOT

Expires: 20 December 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VAUXHALL had different number plates. mber of plates who since

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-30
Last registration	2023-12-19
Complete history	See info



Registration #1	2017-03-30	13 mi
Registration #2	2020-03-14	47.903 mi
Registration #3	2021-03-29	63.714 mi
Registration #4	2021-03-29	63.715 mi
Registration #5		9.772 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	***
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4998 mm
Kerb weight	1743 kg
Max. allowed weight	2820 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MH - C089503LQI

CarCheck.co.uk page 11/11