



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D3 SE
Colour	Blue
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.9 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-22
Pictures	16
Listing price	View report



source: cargurus.co.uk





MOT history

MOT expiry date	2024-09-13
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	9
Total items failed	7

MOT #14	2023-08-16 16:32
MOT test number	997112174238
Result	✓ Passed
Next expiry date	2024-09-13
Advice	Offside Front Play in steering rack inner joint(s)

MOT #13	2022-09-13 11:18
MOT test number	177181102741
Result	✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Inner Play in steering rack inner joint(s)
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #12	2021-09-14 14:41
MOT test number	868536702463
Result	✓ Passed

MOT #11	2020-12-15 15:02
MOT test number	962788446635
Result	✓ Passed

**MOT #10** 2020-01-02 15:39**MOT test number** 587943774510**Result** ✓ Passed**MOT #9** 2019-03-07 10:45**MOT test number** 264434074556**Result** ✓ Passed**MOT #8** 2019-03-07 09:54**MOT test number** 727202361866**Result** ✗ Failed**Fail** Nearside Front All position lamps not working (4.2.1 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-03-07 16:13**MOT test number** 297320277551**Result** ✓ Passed**Advice** Nearside Front wheel has slight damage inner edge**MOT #6** 2018-03-07 09:54**MOT test number** 331268540154**Result** ✗ Failed**Fail** Offside Front Headlamp aim too high (1.8)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front wheel has slight damage inner edge**Fail** Nearside Front Headlamp aim too high (1.8)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #5** 2017-03-03 09:03**MOT test number** 368354446379**Result** ✓ Passed**Advice** Offside Front tyre worn on inner edge**MOT #4** 2016-03-16 09:34**MOT test number** 346768386177**Result** ✓ Passed**MOT #3** 2015-03-19 16:23**MOT test number** 975958175040**Result** ✓ Passed**MOT #2** 2015-03-19 10:52**MOT test number** 926818875004**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2013-10-17 10:24**MOT test number** 248610493243**Result** ✓ Passed**Notice** O/s/r tyre slight uneven tread wear.



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
13 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	13 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-10-22
Last registration	2023-08-16
Complete history	See info



Registration #1	2010-10-22	24 mi
Registration #2	2013-10-17	32.375 mi
Registration #3	2015-03-19	44.908 mi
Registration #4	2015-03-19	44.909 mi
Registration #5	2016-03-16	53.575 mi
Registration #6	2017-03-03	62.243 mi
Registration #7	2018-03-07	71.213 mi
Registration #8	2018-03-07	71.214 mi
Registration #9	2019-03-07	71.217 mi
Registration #10	2019-03-07	71.217 mi
Registration #11	2019-03-07	71.217 mi
Registration #12	2019-03-07	71.217 mi
Registration #13	2019-03-07	71.217 mi
Registration #14	2019-03-07	71.217 mi
Registration #15	2019-03-07	71.217 mi
Registration #16	2019-03-07	71.217 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2775 mm
Kerb weight	1609 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	830610