



WV08YWD

report date: 2024-03-29

General information

Make	FIAT
Model	GRAND PUNTO 16V MULTIJET
Colour	White
Year of manufacture	2008
Top speed	91 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-03
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-09
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	23
Total items failed	9

MOT #19	2024-02-10 09:45
MOT test number	292042518337
Result	✓ Passed
Next expiry date	2025-02-09
Advice	Front Headlamp has a product on the light source but not seriously reducing light output both (4.1.4 (b))
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #18	2023-01-28 14:09
MOT test number	275879847283
Result	✓ Passed

**MOT #17** 2021-12-15 15:32**MOT test number** 104246872462**Result** ✓ Passed

- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2020-11-23 16:40**MOT test number** 427159157924**Result** ✓ Passed**MOT #15** 2020-01-28 14:28**MOT test number** 193467848440**Result** ✓ Passed

- Advice** EXHAUST REAR BOX OUTER SKIN CORRODED
- Advice** Nearside Suspension arm pin or bush worn but not resulting in excessive movement WISHBONE REAR BUSH (5.3.4 (a) (i))

**MOT #14** 2020-01-27 14:39**MOT test number** 685447405830**Result** ✗ Failed

Fail Engine mounting damaged or deteriorated resulting in excessive movement BOTTOM MOUNT (6.1.8 (a) (i))

Advice Nearside Suspension arm pin or bush worn but not resulting in excessive movement WISHBONE REAR BUSH (5.3.4 (a) (i))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice EXHAUST REAR BOX OUTER SKIN CORRODED

MOT #13 2019-03-12 17:05**MOT test number** 208223238987**Result** ✓ Passed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #12 2019-03-12 09:31**MOT test number** 983656008513**Result** ✗ Failed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front discs worn

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #11** 2018-03-26 08:17**MOT test number** 445578625271**Result** ✓ Passed

Advice Offside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #10 2018-03-26 08:17**MOT test number** 119586450085**Result** ✗ Failed

Advice Offside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

MOT #9 2017-03-23 09:36**MOT test number** 779273472196**Result** ✓ Passed**MOT #8** 2016-03-17 09:19**MOT test number** 591063547125**Result** ✓ Passed**MOT #7** 2015-03-27 08:55**MOT test number** 275756185019**Result** ✓ Passed**MOT #6** 2014-03-11 09:25**MOT test number** 146790674435**Result** ✓ Passed

**MOT #5** 2014-03-11 09:25**MOT test number** 165990174028**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #4** 2013-03-15 09:10**MOT test number** 645904673031**Result** ✓ Passed**Notice** Fuel cap seal starting to perish**MOT #3** 2012-03-12 09:46**MOT test number** 685262072008**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-03-22 09:15**MOT test number** 106381781032**Result** ✓ Passed**MOT #1** 2011-03-22 09:15**MOT test number** 826661781045**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 April
------------	---------------------

Days left 337

MOT expiry date	9 February 2025
-----------------	-----------------

Full MOT history [See MOT history](#)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	WV08YWD
Plate since	2019-09-29
Current registration	WV08YWD
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-27
Last registration	2024-02-10
Complete history	See info



Registration #1	2008-03-27	6 mi
Registration #2	2011-03-22	25.867 mi
Registration #3	2012-03-12	34.773 mi
Registration #4	2013-03-15	46.129 mi
Registration #5	2014-03-11	52.185 mi
Registration #6	2015-03-27	58.583 mi
Registration #7	2016-03-17	65.478 mi
Registration #8	2017-03-23	72.780 mi
Registration #9	2018-03-26	80.493 mi
Registration #10	2018-03-26	80.493 mi
Registration #11	2019-03-27	80.493 mi
Registration #12	2019-03-27	80.493 mi
Registration #13	2019-03-27	80.493 mi
Registration #14	2019-03-27	80.493 mi
Registration #15	2019-03-27	80.493 mi
Registration #16	2019-03-27	80.493 mi
Registration #17	2019-03-27	80.493 mi
Registration #18	2019-03-27	80.493 mi
Registration #19	2019-03-27	80.493 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	2682684