



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI STARTLINE BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2015
Top speed	106 mph
0 - 100 km/h	13.4 seconds
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-18
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	5
Total items failed	5

MOT #8	2024-01-10 11:36
MOT test number	210868390616
Result	✓ Passed
Next expiry date	2025-01-12

MOT #7	2023-01-09 12:40
MOT test number	555266950238
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6	2022-01-12 15:57
MOT test number	579441618692
Result	✓ Passed

MOT #5	2022-01-11 12:51
MOT test number	215433912266
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #4** 2021-01-13 14:55**MOT test number** 983158517290**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2021-01-13 14:55**MOT test number** 509312896663**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #2** 2019-05-21 12:32**MOT test number** 906638745697**Result** ✓ Passed**MOT #1** 2018-05-11 10:21**MOT test number** 416475040900**Result** ✓ Passed**Advice** Oil leak Slight oil leak at rear of engine



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
12 January 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	12 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-26
Last registration	2024-01-10
Complete history	See info



Registration #1	2015-05-26	10 mi
Registration #2	2018-05-11	10.871 mi
Registration #3	2019-05-21	14.622 mi
Registration #4	2021-01-13	36.988 mi
Registration #5	2021-01-13	36.988 mi
Registration #6	2022-05-20	36.988 mi
Registration #7	2022-05-20	36.988 mi
Registration #8	2022-05-20	36.988 mi
Registration #9	2022-05-20	36.988 mi
Registration #10	2024-01-10	36.988 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Wheel base	3 mm
Kerb weight	1566 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	2
Number of axles	2
Engine number	CAYDBF5177