



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT SRI
Colour	Grey
Year of manufacture	-
Top speed	130 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	175 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-08-08
Pictures	17
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-03
Pictures	17
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT #18	2021-11-09 12:51
MOT test number	835782483017
Result	✓ Passed
Next expiry date	2022-11-12
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #17	2020-11-12 09:00
MOT test number	763458261477
Result	✓ Passed
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))

MOT #16	2019-11-13 14:28
MOT test number	791111805443
Result	✓ Passed
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

MOT #15	2019-11-05 09:22
MOT test number	266811828947
Result	✗ Failed
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
MAJOR	Nearside Front Windscreen wiper not working (3.4 (a))

**MOT #14**

2018-10-26 08:30

MOT test number

312115633591

Result

✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge worn to 3mm and bald on inner edge.

(5.2.3 (e))

Advice

Nearside Rear slight bind.

Advice

Nearside Front Tyre worn close to legal limit/worn on edge worn to 2 mm and bald on inner edge.

(5.2.3 (e))

MOT #13

2017-11-03 17:23

MOT test number

932903933575

Result

✓ Passed

Advice

Damp around fuel filter

Advice

Eml on

Advice

Brake pipe slightly corroded front to rear (3.6.B.2c)

MOT #12

2017-11-01 09:22

MOT test number

836630707426

Result

✗ Failed

Fail

Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Advice

Brake pipe slightly corroded front to rear (3.6.B.2c)

Advice

Eml on

Fail

Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

Fail

Nearside Rear Registration plate lamp not working (1.1.C.1d)

Fail

Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Advice

Damp around fuel filter

**MOT #11**

2016-10-25 15:30

MOT test number

506996126408

Result

✓ Passed

Advice Oil leak**Advice** Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Front (2.4.G.2)**Advice** Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Front (2.4.G.2)**Advice** Front to rear brake pipes slight corrosion**Advice** Engine management light on**MOT #10**

2016-10-25 14:02

MOT test number

809630571366

Result

✗ Failed

Fail Offside Registration plate lamp not working (1.1.C.1d)**Advice** Oil leak**Advice** Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Front (2.4.G.2)**Advice** Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Front (2.4.G.2)**Advice** Front to rear brake pipes slight corrosion**MOT #9**

2015-11-05 12:50

MOT test number

649827349707

Result

✓ Passed

Advice Engine oil leak**Advice** Rear tyres wearing on inner edges

**MOT #8**

2015-10-28 00:00

MOT test number

212449655839

Result**✗ Failed****Fail** Nearside Rear rear brake binding (3.7.B.1)**Advice** Rear tyres wearing on inner edges**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Engine oil leak**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**MOT #7**

2014-10-29 11:45

MOT test number

698522604352

Result**✓ Passed****Notice** EML on**Notice** Under-trays fitted obscuring some underside components**Notice** Oil leak**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #6**

2014-10-29 11:45

MOT test number

999962304395

Result**✗ Failed****Notice** EML on**Pass with rectification** Nearside Headlamp aim too low (1.8)**Notice** Under-trays fitted obscuring some underside components**Notice** Oil leak**Pass with rectification** Offside Headlamp aim too low (1.8)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5**

2013-10-29 18:12

MOT test number

147172803319

Result**✓ Passed****Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Engine management light on**MOT #4**

2013-10-29 14:45

MOT test number

485082303405

Result**✗ Failed****Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Engine management light on**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



MOT #3	2012-10-30 09:54
MOT test number	786794902350
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	All tyres wearing on edges
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Engine oil leak
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2011-11-01 14:58
MOT test number	419615201487
Result	✓ Passed

MOT #1	2010-10-08 15:07
MOT test number	533031480245
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DV57NKP
Plate since	2019-03-29
Current registration	 DV57NKP
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-10-15
Last registration	2021-11-09
Complete history	See info



Registration #1	2007-10-15	25 mi
Registration #2	2010-10-08	43.208 mi
Registration #3	2011-11-01	54.269 mi
Registration #4	2012-10-30	67.431 mi
Registration #5	2013-10-29	78.579 mi
Registration #6	2013-10-29	78.579 mi
Registration #7	2014-10-29	91.116 mi
Registration #8	2015-10-28	105.370 mi
Registration #9	2015-11-05	105.646 mi
Registration #10	2016-10-25	122.773 mi
Registration #11	2016-10-25	122.773 mi
Registration #12	2016-10-25	122.773 mi
Registration #13	2016-10-25	122.773 mi
Registration #14	2016-10-25	122.773 mi
Registration #15	2016-10-25	122.773 mi
Registration #16	2016-10-25	122.773 mi
Registration #17	2016-10-25	122.773 mi
Registration #18	2016-10-25	122.773 mi
Registration #19	2016-10-25	122.773 mi
Registration #20	2016-10-25	122.773 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	20KH7953