





General information

MakePEUGEOTModel107 ACCESSColourRedYear of manufacture2012Top speed99 mph0 - 60 mph14.2 secondsGearbox5 speed Manual		
ColourRedYear of manufacture2012Top speed99 mph0 - 60 mph14.2 seconds	Make	PEUGEOT
Year of manufacture 2012 Top speed 99 mph 0 - 60 mph 14.2 seconds	Model	107 ACCESS
Top speed 99 mph 0 - 60 mph 14.2 seconds	Colour	Red
0 - 60 mph 14.2 seconds	Year of manufacture	2012
	Top speed	99 mph
Gearbox 5 speed Manual	0 - 60 mph	14.2 seconds
	Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A







Internet history	
Entry 2	
Date	2022-01-29
Pictures	1
Listing price	View report
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-01-21
Pictures	7
Listing price	View report



source: yesauto.com









MOT history

MOT expiry date	2025-01-27
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	16
Total items failed	1

MOT #12	2024-01-24 12:52
MOT test number	112407529108
Result	✓ Passed
Next expiry date	2025-01-27

MOT #11	2024-01-23 13:17
MOT test number	363994391818
Result	🗙 Failed
DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of i (d) (ii))	its structure (5.2.3
MAJOR Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
DANGEROUSOffside Rear Tyre has a tear, caused by separation or partial failure of its(d) (ii))	structure (5.2.3
MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2023-01-23 17:02
MOT test number	336740063633
Result	✓ Passed





МОТ #9	2023-01-23 12:19
MOT test number	413497556598
Result	× Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR Rear Brakes imb	palanced across an axle Axle 2 (1.2.1 (b) (i))

MOT #8	2022-01-28 11:49
MOT test number	936126925717
Result	✓ Passed

MOT #7	2021-04-30 15:03
MOT test number	442161751243
Result	✓ Passed

MOT #6		2020-02-13 15:04
MOT test	number	684952078090
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.	14 (a) (ii))

MOT #5	2019-02-19 16:13
MOT test number	425016580153
Result	✓ Passed

MOT #4		2018-02-16 12:17
MOT test	number	528230739061
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	





MOT #3		2017-02-18 10:43
MOT test	number	424316212399
Result		✓ Passed
Advice	Offside Rear Rear wheel bearing has slight play slightly noisey (2.6.2)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2016-02-24 15:04
MOT test number	176723859501
Result	✓ Passed
MOT #1	2015-06-04 14:16

	2013-00-04 14.10
MOT test number	997515455105
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	



Tax & MOT check

Tax due: 1 February 2025	✓ Taxed	Expires: 27 January 2025	✓ MOT
Tax status			Valid until 1 February
Days left			279
MOT expiry date			27 January 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		48	

venicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-29
Last registration	2024-01-24
Complete history	<u>See info</u>



Registration #1	2012-06-29	18 mi
Registration #2	2015-06-04	27.581 mi
Registration #3	2016-02-24	27.971 mi
Registration #4	2017-02-18	33.426 mi
Registration #5	2018-02-16	39.193 mi
Registration #6	2019-02-19	45.003 mi
Registration #7	2020-02-13	49.156 mi
Registration #8		11.777 est
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 est
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi





Car features

50225	Air conditioning
50295	
50482	
60501	
60566	
60567	
0569	

Safety ratings		
NCAP rating	****	
Video	<u>see crash video</u>	
Dimensions & weight		
Width		1630 mm
Height		1465 mm
Length		3430 mm
Wheel base		2340 mm
Kerb weight		900 kg
Max. allowed weight		1180 kg
Additional information		
Fuel tank capacity		35
Fuel delivery		Multi-Point Injection
Number of doors		3
Number of seats		4
Number of axles		2
Engine number		7155098