



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D2 ES
Colour	Black
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-01-09
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-16
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	15
Total items failed	7

MOT #13	2023-10-27 08:42
MOT test number	823274641854
Result	✓ Passed
Next expiry date	2024-11-16
Advice	Front Registration plate deteriorated but not likely to be misread minor damage/cracked (0.1 (b))
Advice	Rear Direction indicator slightly discoloured both sides (4.4.3 (a))

MOT #12	2022-11-17 09:56
MOT test number	538513970852
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #11** 2022-01-18 15:26**MOT test number** 914078887356**Result** ✓ Passed**MOT #10** 2021-02-22 15:47**MOT test number** 305654101724**Result** ✓ Passed**MOT #9** 2020-02-20 09:25**MOT test number** 299841427813**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #8** 2019-02-09 10:37**MOT test number** 139500162124**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-02-09 10:37**MOT test number** 376847967063**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2018-02-21 11:20**MOT test number** 886577322374**Result** ✓ Passed**MOT #5** 2018-02-19 09:39**MOT test number** 916487344280**Result** ✗ Failed**Fail** Nearside Headlamp insecure (1.7.3)**MOT #4** 2017-03-21 16:10**MOT test number** 528314111552**Result** ✓ Passed**MOT #3** 2017-03-21 15:17**MOT test number** 758646378543**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Registration plate character(s) incorrectly spaced front and rear (6.3.4a)**MOT #2** 2016-04-05 13:29**MOT test number** 844082519355**Result** ✓ Passed**MOT #1** 2016-04-05 13:29**MOT test number** 690276709934**Result** ✗ Failed**Pass with rectification** Front registration plate character(s) incorrectly spaced front and rear number plates lettering incorrectly spaced, replaced at station (6.3.4a)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm tyre below 1.6mm, repaired at station (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
16 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	16 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>WJ13ZLX</b>
Plate since	2019-09-28
Current registration	<b>WJ13ZLX</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-28
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2013-03-28	22 mi
Registration #2	2016-04-05	26.710 mi
Registration #3	2016-04-05	26.710 mi
Registration #4	2017-03-21	37.233 mi
Registration #5	2017-03-21	37.233 mi
Registration #6	2018-02-19	45.191 mi
Registration #7	2018-02-21	45.191 mi
Registration #8	2019-02-09	61.429 mi
Registration #9	2019-02-09	61.429 mi
Registration #10	2019-02-09	61.429 mi
Registration #11	2019-02-09	61.429 mi
Registration #12	2019-02-09	61.429 mi
Registration #13	2019-02-09	61.429 mi
Registration #14	2019-02-09	61.429 mi
Registration #15	2019-02-09	61.429 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1519 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	2276903
---------------	---------