



SL100FH

report date: 2024-03-29

General information

Make	MAZDA
Model	6 D SPORT
Colour	White
Year of manufacture	2010
Top speed	135 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.183 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	142 g/km
CO2 label	F





MOT history

MOT expiry date	2021-08-09
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	18
Total items failed	11

MOT #13	2020-08-10 14:17
---------	------------------

MOT test number	600093090375
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2021-08-09
------------------	------------

- Advice** Rear axle corroded
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material Section of front to rear (1.1.11 (c))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Exhaust corroded
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Section of front to rear (1.1.11 (c))
- Advice** Front cross member corroded
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12**

2020-08-10 14:17

MOT test number

388022404447

Result**✗ Failed****Advice**

Front cross member corroded

Advice

Offside Rear Brake pipe corroded, covered in grease or other material Section of front to rear (1.1.11 (c))

Advice

Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material Section of front to rear (1.1.11 (c))

Advice

Rear axle corroded

Advice

Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Pass with rectification

Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice

Exhaust corroded

MOT #11

2019-04-18 12:01

MOT test number

328990177334

Result**✓ Passed****MOT #10**

2019-04-17 15:16

MOT test number

646098404797

Result**✗ Failed****Fail**

Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #9

2018-04-17 15:13

MOT test number

911914181825

Result**✓ Passed**

**MOT #8**

2018-04-16 10:04

MOT test number

228649324611

Result

✗ Failed

Fail Nearside Front front brake binding (3.7.B.1)**Fail** Nearside Rear rear brake binding (3.7.B.1)**Advice** Front and rear brake discs corroded**Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)**Fail** Offside Rear rear brake excessively fluctuating (3.7.B.3)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**MOT #7**

2017-04-04 13:56

MOT test number

214874939586

Result

✓ Passed

MOT #6

2016-04-20 17:11

MOT test number

809290783983

Result

✓ Passed

MOT #5

2016-04-20 14:08

MOT test number

803227007159

Result

✗ Failed

Fail Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)



MOT #4	2015-04-13 15:43
---------------	------------------

MOT test number	276563805435
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2014-04-14 09:37
---------------	------------------

MOT test number	575354804137
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-04-12 11:41
---------------	------------------

MOT test number	569402103138
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
---------------	--

MOT #1	2013-04-12 11:41
---------------	------------------

MOT test number	737692303107
------------------------	--------------

Result	✗ Failed
---------------	----------

Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
---------------	--

Pass with rectification	Nearside Headlamp aim too high (1.8)
--------------------------------	--------------------------------------



Tax & MOT check

✕
Untaxed

Tax expired:
18 March 2021

✕
MOT

Expired:
9 August 2021

Tax status	Expired at 18 March 2021
Days left	1139 days too late
MOT expiry date	9 August 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-04-30
Last registration	2020-08-10
Complete history	See info



Registration #1	2010-04-30	7 mi
Registration #2	2013-04-12	75.854 mi
Registration #3	2014-04-14	103.646 mi
Registration #4	2015-04-13	124.780 mi
Registration #5	2016-04-20	135.152 mi
Registration #6	2016-04-20	135.152 mi
Registration #7	2017-04-04	140.259 mi
Registration #8	2019-05-20	151.277 mi
Registration #9	2019-05-20	151.277 mi
Registration #10	2019-05-20	151.277 mi
Registration #11	2019-05-20	151.277 mi
Registration #12	2019-05-20	151.277 mi
Registration #13	2019-05-20	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1555 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10241636