



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT S
Colour	Blue
Year of manufacture	2006
Top speed	129 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	200 Nm at 3.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	42.8 mpg
Consumption combined	31.7 mpg
CO2 emission	211 g/km
CO2 label	K





MOT history

MOT expiry date	2021-11-15
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	36
Total items failed	10

MOT #16 2020-11-11 17:06

MOT test number 280435503691

Result ✓ Passed

Next expiry date 2021-11-15

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear wishbone bush starting to split (5.3.4 (a) (i))

MOT #15 2020-11-11 15:31

MOT test number 862297324931

Result ✗ Failed

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Exhaust has a minor leak of exhaust gases Both centre and rear silencers (6.1.2 (a))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear wishbone bush starting to split (5.3.4 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #14** 2019-11-01 17:00**MOT test number** 783959175343**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #13** 2019-10-28 10:49**MOT test number** 396841450741**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #12** 2018-11-16 16:34**MOT test number** 383816620238**Result** ✓ Passed

**MOT #11**

2018-11-16 09:46

MOT test number

326752719758

Result

✗ Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #10

2018-03-01 09:09

MOT test number

895256651717

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Under trays fitted not allowing full inspection of underside of vehicle

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9

2017-03-01 09:21

MOT test number

931321465792

Result

✓ Passed

Advice Under trays fitted not allowing full inspection of underside of vehicle

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2016-02-29 11:59**MOT test number** 892148273729**Result** ✓ Passed**MOT #7** 2015-03-06 15:29**MOT test number** 139365365003**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #6** 2014-03-10 12:40**MOT test number** 637029364022**Result** ✓ Passed**MOT #5** 2013-02-13 15:52**MOT test number** 647904743044**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Both front tyres wearing low on centre tread depth**MOT #4** 2012-02-20 15:00**MOT test number** 967741552060**Result** ✓ Passed**MOT #3** 2011-02-23 15:16**MOT test number** 139074651406**Result** ✓ Passed**Notice** Both front brake discs starting to wear corroded on inners**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #2	2010-03-05 13:16
MOT test number	123574760472
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Both front brake discs worn and badly scored on inner faces

MOT #1	2009-02-24 15:08
MOT test number	624615759021
Result	✓ Passed
Advice	Front brake disc slightly scored (3.5.1h)
Notice	Rear tyres



Tax & MOT check

✕
Untaxed

Tax expired:
12 January 2021

✕
MOT

Expired:
15 November 2021

Tax status	Expired at 12 January 2021
Days left	1204 days too late
MOT expiry date	15 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VX06MKJ
Plate since	2019-06-29
Current registration	 VX06MKJ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-03-04
Last registration	2020-11-11
Complete history	See info



Registration #1	2006-03-04	27 mi
Registration #2	2009-02-24	33.958 mi
Registration #3	2010-03-05	45.643 mi
Registration #4	2011-02-23	54.523 mi
Registration #5	2012-02-20	63.060 mi
Registration #6	2013-02-13	69.663 mi
Registration #7	2014-03-10	78.585 mi
Registration #8	2015-03-06	83.711 mi
Registration #9	2016-02-29	88.460 mi
Registration #10	2016-03-29	91.377 mi
Registration #11	2016-04-29	94.294 mi
Registration #12	2016-05-29	97.211 mi
Registration #13	2016-06-29	100.128 mi
Registration #14	2016-07-29	103.045 mi
Registration #15	2016-08-29	105.962 mi
Registration #16	2016-09-29	108.879 mi
Registration #17	2016-10-29	111.796 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1613 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BVY 020520