





report date: 2024-03-29

### General information

Make	FORD
Model	MONDEO TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

#### Entry 2

Date 2021-10-28

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date 2021-09-10

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



2021-07-21 10:40

MOT history

MOT #10

MOT expiry date	2024-08-02
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	23
Total items failed	2

MOT #12	2023-08-03 16:19
MOT test number	639604341680
Result	<b>✓</b> Passed
Next expiry date 2024-	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #11		2022-08-03 11:35
MOT test	number	255966207844
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT test number	886585683825
Result	✓ Passed
MOT #9	2021-07-21 10:40
MOT test number	415546333569
Result	<b>★</b> Failed
Pass with rectification (4.2.3 (c))	Nearside Rear Position lamp adversely affected by the operation of another lamp
Pass with rectification lamp (4.2.3 (c))	Nearside Front Position lamp adversely affected by the operation of another

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

157643622880

Result

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7		2019-07-24 08:32
MOT test	number	585715160453
Result		✓ Passed
Minor (i))	Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting	surface (4.8.1 (a)
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Nail in tyre	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #6		2018-07-27 11:16
MOT test	number	297577370256
Result		✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front wiper blade smearing slightly.	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5 2017-06-28 13:56

**MOT test number** 224607110214

Result \rightarrow Passed

**Advice** 

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #4 2016-06-27 16:25

MOT test number 306280598009

Result \( \sqrt{Passed} \)

Advice Offside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)

MOT #3 2015-07-10 12:11

**MOT test number** 868631395133

**Result** ✓ Passed

**Notice** Nail in offside rear tyre

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)

MOT #2 2014-09-09 16:51

**MOT test number** 629502554299

**Result** ✓ Passed

**MOT #1** 2013-08-28 09:12

MOT test number 795770743283

**Notice** Under-trays fitted obscuring some underside components

**Notice** Slight roughness in offside front wheel bearing

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	2 August 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-13
Last registration	2023-08-03
Complete history	See info



Registration #1	2010-09-13	7 mi
Registration #2	2013-08-28	47.096 mi
Registration #3	2014-09-09	64.441 mi
Registration #4	2015-07-10	76.145 mi
Registration #5	2016-06-27	88.459 mi
Registration #6	2017-06-28	98.247 mi
Registration #7	2018-07-27	110.780 mi
Registration #8	2019-07-24	122.149 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		71,777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin	
50295		
60482		
60501		
60566		
60567		
60569		

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1571 kg
Max. allowed weight	2180 kg

### Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

**Engine number** AP54091