





General information

Make	CITROEN
Model	C3 DSTYLE PLUS
Colour	Blue
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	57.7 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F







Internet history

Entry 1	
Date	2021-01-29
Pictures	10
Listing price	View report









source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-25
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	17
Total items failed	1

MOT #10	2024-04-22 11:11
MOT test number	129931136577
Result	✓ Passed
Next expiry date	2025-04-25

MOT #9	2023-04-26 11:49
MOT test number	806000547754
Result	Passed
Advice Child Seat fitted not allowing full inspection of adult belt	

MOT #8	2023-04-15 10:15	5
MOT test	number 812169914452	2
Result	× Failed	1
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
MAJOR (i))	R Offside Front Inner Suspension arm pin or bush excessively worn Excessive movement (5.3.4 (a)	
Advice	Child Seat fitted not allowing full inspection of adult belt	
MAJOR (i))	Nearside Front Inner Suspension arm pin or bush excessively worn Excessive movement (5.3.4 (a)	





MOT #7		2022-04-21 09:24
MOT test	number	511618708621
Result		✓ Passed
Advice	Front Exhaust mounting defective starting to come away from the exhaust p	ipe (6.1.2 (a))
MOT #6		2021-04-20 12:51
MOT test	number	826289070152
Result		✓ Passed
MOT #5		2020-09-07 10:36
MOT test	number	719942961208
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #4		2019-09-05 11:17
MOT test	number	765161813305
Result		🗸 Passed
Advice Rear Exhaust mounting defective rear mounting broken, system supported. (6.1.2 (a))		
Advice	Advice Nearside Rear Tyre slightly damaged/cracking or perishing perishing. (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perishing. (5.2.3 (d) (ii))	





MOT #3		2019-09-05 11:17
MOT test r	number	624845225088
Result		× Failed
Pass wit	h rectification	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)
Advice Nearside Rear Tyre slightly damaged/cracking or perishing perishing. (5.2.3 (d) (ii))		
Advice Rear Exhaust mounting defective rear mounting broken, system supported. (6.1.2 (a))		
Advice Offside Rear Tyre slightly damaged/cracking or perishing perishing. (5.2.3 (d) (ii))		

MOT #2	2018-09-14 14:23	2
MOT test	number 56891444236	6
Result	✓ Passed	d
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened worn (1.1.14 (a) (ii))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened worn (1.1.14 (a) (ii))	

MOT #1	2017-09-22 09:02
MOT test number	592030403817
Result	✓ Passed



GN64RCV report date: 2024-03-29

Tax & MOT check

✓ Taxed	√ мот
Tax due: 1 April 2025	Expires: 25 April 2025
Tax status	Valid until 1 April
Days left	336
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	 · · ·
Category	 AMPL
Туре	

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-30
Last registration	2024-04-22
Complete history	See info



Registration #1	2014-09-30	25 mi
Registration #2	2017-09-22	29.196 mi
Registration #3	2018-09-14	38.710 mi
Registration #4	2019-09-05	45.400 mi
Registration #5	2019-09-05	45.400 mi
Registration #6	2020-09-07	51.884 mi
Registration #7		11.777 mi
Registration #7 Registration #8		00.000 est
-		01.000 est 01.000 est 01.000 est
Registration #8		00.000 est 0.000 est 00.000 est 00.000 est
Registration #8 Registration #9		01.000 est 0.000 est 01.000 est 01.000 est 01.000 est





Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1145 kg
Max. allowed weight	1587 kg
Additional information	
Additional information Fuel tank capacity	48
	48 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 3