



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D SE SPORT
Colour	Black
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-19
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #17

2023-05-17 10:08

MOT test number

587041523489

Result

✓ Passed

Next expiry date

2024-05-16

- Advice** Lower Gearbox mounting defective
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside front drive shaft bearing slightly noisy
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Tyre worn close to legal limit/worn on edge Both front and cracking (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Front and Rear (1.1.14 (a) (ii))
- Advice** Parking brake lever travel
- Advice** Coil spring corroded Both rear (5.3.1 (b) (i))

MOT #16

2022-03-31 08:36

MOT test number

281084455957

Result

✓ Passed

- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**MOT #15** 2022-03-31 08:36**MOT test number** 123215770594**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**MOT #14** 2021-03-12 15:40**MOT test number** 878767692318**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front tyres worn close to markers**MOT #13** 2020-02-06 14:44**MOT test number** 389844583691**Result** ✓ Passed**MOT #12** 2020-01-29 16:08**MOT test number** 853186404243**Result** ✗ Failed**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Supplementary restraint system warning lamp indicates a fault air bag (7.1.6 (a))**MOT #11** 2019-01-23 13:14**MOT test number** 916260972114**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2018-02-08 13:15**MOT test number** 635206580818**Result** ✓ Passed**Advice** Signs of oil leak, unable to find cause due to undertrays**MOT #9** 2017-02-13 10:53**MOT test number** 874364037855**Result** ✓ Passed**MOT #8** 2016-01-29 12:44**MOT test number** 775020686573**Result** ✓ Passed**Advice** Rear exhaust box outer cover corroded**Advice** Nearside Rear tyre close to legal limit on 2mm**MOT #7** 2015-01-17 12:33**MOT test number** 758857315025**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear silencer in poor condition



MOT #6	2014-03-15 10:01
MOT test number	395674674010
Result	✓ Passed
<div>Notice Advise middle exhaust box breaking up</div>	

MOT #5	2014-03-14 11:33
MOT test number	415693674092
Result	✗ Failed
<div><div>Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)</div><div>Fail Offside Front coil spring broken (2.4.C.1a)</div><div>Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)</div><div>Fail Nearside Front coil spring broken (2.4.C.1a)</div><div>Notice Advise middle exhaust box breaking up</div></div>	

MOT #4	2013-03-08 12:02
MOT test number	909147863076
Result	✓ Passed
<div><div>Notice Engine covers fitted obscuring some components in the engine bay</div><div>Advice Front Brake pad(s) wearing thin (3.5.1g)</div><div>Notice Under-trays fitted obscuring some underside components</div></div>	



MOT #3	2013-03-07 09:42
MOT test number	705636263077
Result	✗ Failed
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Under-trays fitted obscuring some underside components
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2012-03-14 14:16
MOT test number	847144672029
Result	✓ Passed
MOT #1	2011-03-18 11:23
MOT test number	736917071067
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-31
Last registration	2023-05-17
Complete history	See info



Registration #1	2008-03-31	19 mi
Registration #2	2011-03-18	30.638 mi
Registration #3	2012-03-14	40.399 mi
Registration #4	2013-03-07	49.642 mi
Registration #5	2013-03-08	49.643 mi
Registration #6	2014-03-14	59.140 mi
Registration #7	2014-03-15	59.140 mi
Registration #8	2015-01-17	64.834 mi
Registration #9	2016-01-29	83.781 mi
Registration #10	2017-02-13	102.361 mi
Registration #11	2018-03-20	121.277 mi
Registration #12	2019-03-20	140.193 mi
Registration #13	2020-03-20	159.109 mi
Registration #14	2021-03-20	178.025 mi
Registration #15	2022-03-20	196.941 mi
Registration #16	2023-03-20	215.857 mi
Registration #17	2024-03-20	234.773 mi
Registration #18	2025-03-20	253.689 mi
Registration #19	2026-03-20	272.605 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1414 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	445775