



report date: 2024-03-29

General information

Make	FIAT
Model	GRAND PUNTO ACTIVE
Colour	Red
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-07-15
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-28
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	39
Total items failed	14

MOT #19	2023-07-25 15:01
MOT test number	556013453073
Result	✓ Passed
Next expiry date	2024-07-28
Advice	Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #18	2023-07-25 11:45
MOT test number	923029071964
Result	✗ Failed
Advice	Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Fail	Front Exhaust has a major leak of exhaust gases Flexi & front joint (6.1.2 (a))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Emissions unable to be completed Due to exhaust leak (8.2.1.2 (d))

**MOT #17**

2022-07-29 11:00

MOT test number

218785869547

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #16**

2022-07-26 15:01

MOT test number

506990161881

Result

✗ Failed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2020-11-14 15:07

MOT test number

409224889402

Result

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #14

2019-11-12 09:51

MOT test number

205485977865

Result

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #13**

2019-11-12 09:51

MOT test number

774700882944

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

MOT #12

2018-11-15 11:14

MOT test number

100311605003

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2018-11-15 09:18

MOT test number

926489073648

Result**✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))



MOT #10	2017-12-01 11:08
MOT test number	285577480329
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #9	2017-11-24 09:21
MOT test number	878805686125
Result	✗ Failed
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
Advice	Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #8	2016-12-05 12:56
MOT test number	342928149389
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7	2016-12-05 10:10
MOT test number	296857318658
Result	✗ Failed
Fail	Offside Rear Shock absorber has a serious fluid leak (2.7.3)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)

**MOT #6** 2015-11-25 09:10**MOT test number** 701634260263**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit worn close on edge (4.1.E.1)**MOT #5** 2014-11-06 09:07**MOT test number** 226410314348**Result** ✓ Passed**MOT #4** 2013-11-25 12:28**MOT test number** 467279523454**Result** ✓ Passed**MOT #3** 2013-11-25 10:12**MOT test number** 107009423314**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #2** 2012-12-03 11:25**MOT test number** 735318232372**Result** ✓ Passed**MOT #1** 2012-12-03 09:46**MOT test number** 777978332344**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
28 July 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	28 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-29
Current registration	
Plate since	2019-06-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-11-30
Last registration	2023-07-25
Complete history	See info



Registration #1	2009-11-30	23 mi
Registration #2	2012-12-03	38.911 mi
Registration #3	2012-12-03	38.911 mi
Registration #4	2013-11-25	45.832 mi
Registration #5	2013-11-25	45.832 mi
Registration #6	2014-11-06	57.078 mi
Registration #7	2015-11-25	69.825 mi
Registration #8	2016-12-05	81.568 mi
Registration #9	2016-12-05	81.568 mi
Registration #10	2017-11-24	90.329 mi
Registration #11	2017-12-01	90.465 mi
Registration #12	2018-01-01	90.465 mi
Registration #13	2018-01-01	90.465 mi
Registration #14	2018-01-01	90.465 mi
Registration #15	2018-01-01	90.465 mi
Registration #16	2018-01-01	90.465 mi
Registration #17	2018-01-01	90.465 mi
Registration #18	2018-01-01	90.465 mi
Registration #19	2018-01-01	90.465 mi
Registration #20	2018-01-01	90.465 mi
Registration #21	2018-01-01	90.465 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694