



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE NAVIGATION TDI BLUEMOTION TECHNOLOGY
Colour	Grey
Year of manufacture	2018
Top speed	126 mph
0 - 100 km/h	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	85 kW / 116 HP / 114 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	61.4 mpg
CO2 emission	106 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-10-27
Pictures	0
Listing price	<a href="#">View report</a>

source: heycar.co.uk



## MOT history

MOT expiry date	2024-02-02
MOT pass rate	100 %
MOT passed	3
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #3 2023-02-03 09:46

MOT test number 975920620550

Result ✓ Passed

Next expiry date 2024-02-02

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm in center (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm in center (5.2.3 (e))

MOT #2 2021-10-29 15:47

MOT test number 770516725859

Result ✓ Passed



MOT #1 2021-06-16 09:56

MOT test number 696888233207

Result ✓ Passed

- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✗  
**MOT**  
**Expired:**  
2 February 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	2 February 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>ND18VHA</b>
Plate since	2019-03-29
Current registration	<b>ND18VHA</b>
Plate since	2019-03-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2018-07-16
Last registration	2023-02-03
Complete history	<a href="#">See info</a>



Registration #1	2018-07-16	9 mi
Registration #2	2021-06-16	33.419 mi
Registration #3	2022-05-20	35,377 mi
Registration #4	2022-05-20	35,377 mi
Registration #5	2023-02-03	35,377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2027 mm
Height	1492 mm
Length	4258 mm
Wheel base	2620 mm
Kerb weight	1246 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	DDYA682580