



report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA SE
Colour	Red
Year of manufacture	2004
Top speed	110 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





MOT history

MOT expiry date	2021-10-11
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	28
Total items failed	5

MOT #17	2020-10-12 15:33
MOT test number	524702785176
Result	✓ Passed
Next expiry date	2021-10-11
Advice	Nearside Front Macpherson strut mounting corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i))
Advice	Nearside Rear Fuel Pipe/s corroded
Advice	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #16**

2020-10-12 14:39

MOT test number

799811874327

Result**✗ Failed****MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Front Macpherson strut mounting corroded but not seriously weakened (5.3.3 (b) (i))**MAJOR** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i))**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Nearside Rear Fuel Pipe/s corroded**MOT #15**

2019-04-08 15:52

MOT test number

492754142518

Result**✓ Passed****Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Strut top mounting slightly rough to turn**MOT #14**

2018-03-24 13:17

MOT test number

817458935639

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #13** 2017-04-11 10:39**MOT test number** 107462944733**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases flange joint before rear silencer (7.1.2)**Advice** Nearside Front brake has a very slight bind**MOT #12** 2016-05-13 08:57**MOT test number** 517752585685**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-05-13 08:57**MOT test number** 473223794766**Result** ✗ Failed**Pass with rectification** Nearside Front front brake binding (3.7.B.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2015-05-01 11:11**MOT test number** 607721625147**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #9** 2014-05-15 14:38**MOT test number** 319925134120**Result** ✓ Passed

**MOT #8** 2014-05-10 12:42**MOT test number** 798320234105**Result** ✗ Failed

- Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)
- Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #7 2013-04-27 13:10**MOT test number** 445267013181**Result** ✓ Passed

- Notice** O/s/f tyre edge close to limit
- Notice** N/s/f tyre edge close to limit

MOT #6 2012-04-24 10:54**MOT test number** 277505112431**Result** ✓ Passed

- Notice** N/s/f wipper blade torn

MOT #5 2011-05-03 10:00**MOT test number** 808313021192**Result** ✓ Passed**MOT #4** 2010-05-01 11:09**MOT test number** 203261520470**Result** ✓ Passed



MOT #3	2009-05-06 16:46
MOT test number	462676929199
Result	✓ Passed
MOT #2	2008-10-07 15:07
MOT test number	451521688288
Result	✓ Passed
MOT #1	2007-10-05 10:32
MOT test number	120278277231
Result	✓ Passed



Tax & MOT check

×

Untaxed

Tax expired:
16 December 2020

×

MOT

Expired:
11 October 2021

Tax status

Expired at 16 December 2020

Days left

1230 days too late

MOT expiry date

11 October 2021

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-10-08
Last registration	2020-10-12
Complete history	See info



Registration #1	2004-10-08	18 mi
Registration #2	2007-10-05	14.327 mi
Registration #3	2008-10-07	17.728 mi
Registration #4	2009-05-06	19.697 mi
Registration #5	2010-05-01	24.609 mi
Registration #6	2011-05-03	28.744 mi
Registration #7	2012-04-24	31.953 mi
Registration #8	2013-04-27	35.164 mi
Registration #9	2014-05-10	38.224 mi
Registration #10	2015-05-10	41.284 mi
Registration #11	2016-05-10	44.344 mi
Registration #12	2017-05-10	47.404 mi
Registration #13	2018-05-10	50.464 mi
Registration #14	2019-05-10	53.524 mi
Registration #15	2020-05-10	56.584 mi
Registration #16	2021-05-10	59.644 mi
Registration #17	2022-05-10	62.704 mi
Registration #18	2023-05-10	65.764 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1179 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	267070