





report date: 2024-03-28

#### General information

Make	NISSAN
Model	PATHFINDER DCI TEKNA
Colour	Black
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 3.600 rpm
Engine capacity	2.488 сс
Cylinders	4
Fuel type	Diesel
Consumption city	24.1 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L



CarCheck.co.uk page 1/13



## Internet history

Entry	1

Life y 1	
Date	2022-02-18
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2025-03-03
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	13
Total items failed	14

MOT #15	2024-03-04 18:17
MOT test number	585797384220
Result	✓ Passed
Next expiry date	2025-03-03

MOT #14	2022-04-06 07:58
MOT test number	282088293806
Result	<b>√</b> Passed
Advice Front FLEXI SECTION BLOWING	
Advice UNDERSIDE CORRODED	

MOT #13	2022-03-17 15:47
MOT test number	385982728938
Result	✓ Passed
Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice Underside corroded	

MOT #12	2021-02-18 14:52
MOT test number	324868124266
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #11** 2021-02-17 10:59 **MOT** test number 423003132015 Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Front Prop shaft joint excessively worn (6.1.7 (c) (i)) Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Fail **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

MOT test number

483679811441

Result

✓ Passed

MOT #9

MOT test number 558965380605

Result × Failed

Pass with rectification Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

Pass with rectification Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Pass with rectification Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #8 2019-02-27 10:02

MOT test number 561502860083

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7

MOT test number

532182118658

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.2b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.2b)

**MOT** #6 2018-02-20 10:34 **MOT** test number 720612102063 Result **X** Failed Nearside Front Tyre worn close to the legal limit (4.1.E.2b) **Advice** Fail Offside Rear coil spring broken (2.4.C.1a) Fail Offside Rear Tyre tread depth below requirements of 1.0mm (4.1.E.2b) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.2b) Fail Nearside Rear Tyre tread depth below requirements of 1.0mm (4.1.E.2b)

 MOT #5
 2017-02-15 10:57

 MOT test number
 265205651817

 Result
 ✓ Passed

 MOT #4
 2017-02-13 11:25

 MOT test number
 590521277181

 Result
 X Failed

 Fail
 Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

 MOT #2
 2016-02-11 12:24

 MOT test number
 680536142069

 Result
 ✓ Passed

MOT #1

MOT test number

246682584557

Result

Pass with rectification

Offside Rear fog lamp not working (1.3.2b)

CarCheck.co.uk page 6/13



#### Tax & MOT check





Tax status	Expired at 31 May 2022
Days left	698 days too late
MOT expiry date	3 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vahiela elega	40
Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

*		
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full r		ιN
********		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes  See in this check if this NISSAN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-03-01
Last registration	2024-03-04
Complete history	See info



Registration #1	2013-03-01	19 mi
Registration #2	2016-02-11	38.477 mi
Registration #3	2016-02-11	38.477 mi
Registration #4	2017-02-09	51.786 mi
Registration #5	2017-02-13	51.875 mi
Registration #6	2017-02-15	51.876 mi
Registration #7	2018-02-20	65.584 mi
Registration #8	2018-02-21	65.584 mi
Registration #9	2019-02-27	79.835 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.70 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1848 mm
Height	1785 mm
Length	4813 mm
Wheel base	2853 mm
Kerb weight	2160 kg
Max. allowed weight	2880 kg

# Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1

Number of axles 2
Engine number 89693B