



report date: 2024-03-28

General information

Make	FIAT
Model	GRAND PUNTO SOUND
Colour	Black
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg





Internet history

**Entry 1**

Date	2021-07-23
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

<b>MOT #13</b>	2023-09-29 12:43
<b>MOT test number</b>	359979324210
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-09-28
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Front Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #12</b>	2023-09-29 12:43
<b>MOT test number</b>	858656951157
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
<b>Advice</b>	Front Direction indicator slightly discoloured (4.4.3 (a))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Pass with rectification</b>	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #11</b>	2022-08-05 11:57
<b>MOT test number</b>	439592085155
<b>Result</b>	✓ Passed
<b>Advice</b>	Tyre worn close to legal limit/worn on edge all (5.2.3 (e))

<b>MOT #10</b>	2021-07-27 09:32
<b>MOT test number</b>	626901794170
<b>Result</b>	✓ Passed



**MOT #9** 2021-07-07 11:33

**MOT test number** 689676598817

**Result** ✗ Failed

- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Items removed from driver's view prior to test
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #8** 2020-07-28 13:53

**MOT test number** 171157045944

**Result** ✓ Passed

- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #7** 2019-05-31 10:16

**MOT test number** 438330112946

**Result** ✓ Passed

**MOT #6** 2018-06-13 14:33

**MOT test number** 841395141527

**Result** ✓ Passed

- Advice** Covers & shields fitted

**MOT #5** 2017-09-27 09:12

**MOT test number** 551998258178

**Result** ✓ Passed



<b>MOT #4</b>	2016-09-23 09:28
<b>MOT test number</b>	550651313494
<b>Result</b>	✓ Passed
<b>Advice</b>	O/s/r tyre perished

<b>MOT #3</b>	2015-09-18 12:22
<b>MOT test number</b>	295519119899
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2014-09-22 12:28
<b>MOT test number</b>	637515064281
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2013-09-27 10:51
<b>MOT test number</b>	317120773447
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>LR10UYP</b>
Plate since	2019-09-29
Current registration	<b>LR10UYP</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-04-29
Last registration	2023-09-29
Complete history	<a href="#">See info</a>



Registration #1	2010-04-29	8 mi
Registration #2	2013-09-27	25.000 mi
Registration #3	2014-09-22	33.477 mi
Registration #4	2015-09-18	42.343 mi
Registration #5	2016-09-23	50.356 mi
Registration #6	2017-09-27	59.005 mi
Registration #7	2018-06-13	63.732 mi
Registration #8	2019-05-31	66.564 mi
Registration #9	2020-05-31	69.391 mi
Registration #10	2021-05-31	72.218 mi
Registration #11	2022-05-31	75.045 mi
Registration #12	2023-05-31	77.872 mi
Registration #13	2023-09-29	80.699 mi
Registration #14	2023-09-29	80.699 mi
Registration #15	2023-09-29	80.699 mi

[More info >](#)



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

9632561