





report date: 2024-03-29

### General information

Make	FORD
Model	FUSION ZETEC TDCI
Colour	Blue
Year of manufacture	2009
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-29

### Internet history

### Entry 1

Date 2021-09-09

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-09-19
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	8
Total items failed	5

MOT #17	2023-09-11 09:41
MOT test number	102527134632
Result	✓ Passed
Next expiry date	2024-09-19

MOT #16	2022-09-06 07:41
MOT test number	484065003734
Result	✓ Passed

MOT #15		2021-09-20 12:06
MOT test	number	514469864119
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Exhaust silencer slightly loose (8.1.1 (b) (i))	

MOT #14	2020-12-11 10:58
MOT test number	425859285637
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13 2020-12-11 10:58

**MOT test number** 626693768872

Result X Failed

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #12 2019-12-18 12:48

**MOT test number** 764591098692

**Result** ✓ Passed

**MOT #11** 2018-12-17 11:17

**MOT test number** 919763142343

**Result** ✓ Passed

**MOT #10** 2018-12-17 11:17

**MOT test number** 932641291995

**Result** ★ Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

MOT #9 2017-12-14 09:36

MOT test number 581764897775

Result 

Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside and nearside front tyres worn on inner edges

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2016-12-15 15:45

**MOT test number** 238790191598

Result 

Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7 2016-12-15 12:10

MOT test number 136749480273

**Result** X Failed

**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #6 2015-12-17 11:41

MOT test number 131564938493

**MOT #5** 2015-12-17 11:41

**MOT test number** 992348212268

Result X Failed

**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

**MOT #4** 2014-12-19 09:57

**MOT test number** 438423754385

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-12-18 16:18

**MOT test number** 499962754380

**Result** X Failed

**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2013-12-13 10:26

**MOT test number** 777817543333

**Result** ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2012-12-17 14:20

**MOT test number** 476662652404

**Result** ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

### Tax & MOT check





**Expires:** 19 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	19 September 2024
Full MOT history	See MOT history

### Tax calculation

Vahiala alaas	40
Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
***************************************	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK SILVE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-12-30
Last registration	2023-09-11
Complete history	See info



Registration #1	2009-12-30	29 mi
Registration #2	2012-12-17	22.779 mi
Registration #3	2013-12-13	31.975 mi
Registration #4	2014-12-18	43.540 mi
Registration #5	2014-12-19	43.540 mi
Registration #6	2015-12-17	55.633 mi
Registration #7	2015-12-17	55.633 mi
Registration #8	2016-12-15	65.690 mi
Registration #9	2016-12-15	65.690 mi
Registration #10	2017-12-14	76.852 mi
Registration #11		71.777 66
Registration #12		77.777 44
Registration #13		71.777 66
Registration #14		77.777 46
Registration #15		71.777 66
Registration #16		77.777 46
Registration #17		71.777 66
D		
Registration #18		11.777 au
Registration #19		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	***
Video	see crash video



## Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1162 kg
Max. allowed weight	1640 kg

## Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles Carcheck.co.uk	2	page 13/13