



report date: 2024-03-28

General information

Make	FIAT
Model	DUCATO 35 C/C MULTIJET
Colour	White
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	2.999 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	192 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-26
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-12
MOT pass rate	50 %
MOT passed	5
Failed MOT tests	5
Total advice items	37
Total items failed	2

MOT #10	2023-10-12 14:43
MOT test number	251886582810
Result	✓ Passed
Next expiry date	2024-10-12
Minor	Nearside Outline marker lamp with a multiple light source up to 1/2 not functioning all ns not working propley (4.2.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9**

2023-10-11 07:48

MOT test number

760708463599

Result**✗ Failed****MAJOR** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Central Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush poor (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Outline marker lamp with a multiple light source up to 1/2 not functioning all ns not working properly (4.2.1 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))**MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #8**

2022-10-13 10:24

MOT test number

424237249214

Result**✓ Passed****Advice** Front Suspension arm ball joint has slight play both sides (5.3.4 (a) (i))**Advice** Front Passenger seat(s) missing at time of test**MOT #7**

2022-10-13 10:24

MOT test number

454471056714

Result**✗ Failed****Advice** Front Passenger seat(s) missing at time of test**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Pass with rectification** Windscreen washer not working (3.5 (a))**Advice** Front Suspension arm ball joint has slight play both sides (5.3.4 (a) (i))

**MOT #6** 2021-10-04 11:42**MOT test number** 271052903391**Result** ✓ Passed**MOT #5** 2021-10-01 13:30**MOT test number** 367839992174**Result** ✗ Failed**MAJOR** Nearside Outline marker lamp likely to become detached (4.2.1 (c) (ii))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Play in steering rack inner joint(s)**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #4** 2021-02-19 15:45**MOT test number** 996681176085**Result** ✓ Passed**Minor** Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Brake pads indicator wire damaged**Advice** Nearside Front Brake pads wear indicator wire damaged**Advice** Offside Play in steering rack inner joint(s)

**MOT #3**

2021-02-18 09:52

MOT test number

288487980776

Result**✗ Failed****Advice**

Offside Front Body panel missing

Advice

Offside Front Brake pads indicator wire damaged

MAJOR

Nearside Front Lower Outline marker lamp missing (4.2.1 (a) (ii))

Advice

Offside Play in steering rack inner joint(s)

Advice

Nearside Front Body panel missing

Advice

Nearside Front Brake pads wear indicator wire damaged

MAJOR

Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Minor

Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MAJOR

Offside Front Lower Outline marker lamp missing (4.2.1 (a) (ii))

MOT #2

2020-02-19 16:21

MOT test number

761453858599

Result**✓ Passed****MOT #1**

2020-02-19 10:56

MOT test number

803537460097

Result**✗ Failed****Advice**

Front Brake disc worn, but not excessively Both sides (1.1.14 (a) (i))

Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR

Nearside Rear Outline marker lamp not working (4.2.1 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
12 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-03-13
Last registration	2023-10-12
Complete history	See info



Registration #1	2017-03-13	26 mi
Registration #2	2020-02-19	47.978 mi
Registration #3	2020-02-19	47.978 mi
Registration #4	2021-02-18	61.427 mi
Registration #5	2021-02-19	61.427 mi
Registration #6	2023-10-12	61.427 mi
Registration #7	2023-10-12	61.427 mi
Registration #8	2023-10-12	61.427 mi
Registration #9	2023-10-12	61.427 mi
Registration #10	2023-10-12	61.427 mi
Registration #11	2023-10-12	61.427 mi
Registration #12	2023-10-12	61.427 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2050 mm
Height	2254 mm
Length	6328 mm
Kerb weight	1655 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	2635176