





report date: 2024-03-28

### General information

Make	BMW
Model	X5 XDRIVE40D M SPORT
Colour	Grey
Year of manufacture	2018
Top speed	149 mph
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.8 mpg
CO2 emission	183 g/km
CO2 label	ı



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

### Entry 1

Date 2022-01-11

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-11-29
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	14
Total items failed	7

MOT #5	2023-11-30 17:51
MOT test number	755161154458
Result	✓ Passed
Next expiry date	2024-11-29

MOT #4	2023-01-26 08:54
MOT test number	846656701302
Result	✓ Passed

CarCheck.co.uk page 3/12



**MOT #3** 

**Advice** 

**Advice** 

Fail

Fail

**Minor** 

(e))

**GV18ERZ** 

report date: 2024-03-28

2023-01-19 12:15

**MOT** test number 967380180231 Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge Tyre devoid of tread inner edge (5.2.3 (e)) Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Front Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Nearside Rear Tyre worn close to legal limit/worn on edge Tyre devoid of tread inner edge (5.2.3

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Nearside Front Tyre obviously under inflated (5.2.3 (I))

Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #2

2022-01-24 09:13

MOT test number

825196226476

Result

Advice

Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front washer jet weak

Advice

Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #1 2021-05-17 11:46

MOT test number

Result

Advice
Offside Rear Nail in tyre

Advice
Rear Tyre worn close to legal limit/worn on edge both rear tyres wearing on inner edges (5.2.3 (e))

Advice
Nearside Rear Tyre slightly damaged/cracking or perishing cut in tread, but not to cord (5.2.3 (d) (ii))

Advice
Tyre slightly damaged/cracking or perishing front and rear tyres slightly cracking/ perished (5.2.3 (d) (iii))

CarCheck.co.uk page 5/12



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	29 November 2024
Full MOT history	See MOT history

### Tax calculation

-	
Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	
manage of the same	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-06-15
Last registration	2023-11-30
Complete history	See info



Registration #1	2018-06-15	21 mi
Registration #2	2021-05-17	16.255 mi
Registration #3		11.777 es
Registration #4	2022-01-24	20.743 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1989 mm
Height	1702 mm
Length	4909 mm
Wheel base	2933 mm
Kerb weight	2105 kg
Max. allowed weight	2820 kg

### Additional information

Fuel tank capacity	85 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles2Engine number67045429