



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT TSI CC
Colour	Black
Year of manufacture	2009
Top speed	138 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.2 mpg
CO2 emission	178 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2023-12-01
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	33
Total items failed	12

MOT #15	2022-12-02 13:50
MOT test number	725774392406
Result	✓ Passed
Next expiry date	2023-12-01
Advice	Full under covers fitted obscuring some components
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2022-11-29 14:38

**MOT test number**

569574577669

**Result****✗ Failed****Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Rear All position lamps have a product on the lenses or light sources which obviously reduces light intensity (4.2.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Fluid leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Minor** Offside Rear All position lamps have a product on the lenses or light sources which obviously reduces light intensity (4.2.3 (b) (i))**Advice** Large undertrays fitted restricting inspection of some items**Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #13**

2021-06-08 12:41

**MOT test number**

593257039841

**Result****✓ Passed****MOT #12**

2020-08-18 13:08

**MOT test number**

554375655081

**Result****✓ Passed****Advice** Rear brake pads 60% worn

**MOT #11** 2019-08-16 09:15**MOT test number** 434010498991**Result** ✓ Passed**MOT #10** 2018-08-14 10:01**MOT test number** 181546055326**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Front and rear (1.1.14 (a) (ii))**MOT #9** 2017-07-19 15:26**MOT test number** 175698596785**Result** ✓ Passed**MOT #8** 2016-09-15 13:04**MOT test number** 791382152099**Result** ✓ Passed**MOT #7** 2016-09-15 12:09**MOT test number** 472403763608**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2015-09-16 08:54**MOT test number** 293807447451**Result** ✓ Passed**Advice** Both rear tyres lumpy + cracks in sidewall

**MOT #5**

2014-09-13 09:34

**MOT test number**

489036954215

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Spare tyre defective
- Advice** Nearside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Both rear tyres heavily perished
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components

**MOT #4**

2014-09-13 09:23

**MOT test number**

148326454201

**Result**

✗ Failed

- Fail** Nearside Headlamp aim too low (1.8)
- Notice** Both rear tyres heavily perished
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Headlamp aim too low (1.8)
- Notice** Spare tyre defective
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #3 2013-09-14 08:50

MOT test number 847427153263

Result ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Items removed from driver's view prior to test

MOT #2 2013-09-14 08:50

MOT test number 655937753228

Result ✗ Failed

**Notice** Items removed from driver's view prior to test

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

MOT #1 2012-09-20 15:45

MOT test number 257024162223

Result ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:  
7 June 2023

X

MOT

Expired:  
1 December 2023

Tax status	Expired at 7 June 2023
Days left	328 days too late
MOT expiry date	1 December 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>NK59GWE</b>
Plate since	2024-03-29
Current registration	 <b>NK59GWE</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-14
Last registration	2022-12-02
Complete history	<a href="#">See info</a>



Registration #1	2009-09-14	12 mi
Registration #2	2012-09-20	20.272 mi
Registration #3	2013-09-14	26.191 mi
Registration #4	2014-09-13	33.433 mi
Registration #5	2014-09-13	33.433 mi
Registration #6	2015-09-16	41.567 mi
Registration #7	2016-09-15	46.971 mi
Registration #8	2016-09-15	46.979 mi
Registration #9	2016-09-15	46.979 mi
Registration #10	2016-09-15	46.979 mi
Registration #11	2016-09-15	46.979 mi
Registration #12	2016-09-15	46.979 mi
Registration #13	2016-09-15	46.979 mi
Registration #14	2016-09-15	46.979 mi
Registration #15	2016-09-15	46.979 mi
Registration #16	2016-09-15	46.979 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1417 mm
Length	4799 mm
Wheel base	2708 mm
Kerb weight	1430 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	4
Number of axles	2
Engine number	BZB 107464