



DUI2VWE

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V
Colour	White
Year of manufacture	2012
Top speed	98 mph
0 - 60 mph	15.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-28
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-25
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	16
Total items failed	13

MOT #14	2024-04-22 13:44
MOT test number	269643842345
Result	✓ Passed
Next expiry date	2025-04-25
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2024-04-22 08:06
MOT test number	718134862709
Result	✗ Failed
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #12	2023-04-19 15:49
MOT test number	199992859258
Result	✓ Passed
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #11** 2022-04-25 07:53**MOT test number** 125331192371**Result** ✓ Passed**MOT #10** 2022-04-20 10:02**MOT test number** 539030713713**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #9** 2021-04-26 12:55**MOT test number** 525597857939**Result** ✓ Passed**Advice** O/S/F fog light very dull and flickering.**Minor** Offside Front Obligatory mirror slightly loose mirror glass. (3.3 (b) (i))**MOT #8** 2021-04-13 13:58**MOT test number** 394190598220**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps Both rear lights inop (4.7.1 (b) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords very poor inner edges (5.2.3 (d) (i))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords very poor inner edges. (5.2.3 (d) (i))**Advice** O/S/F fog light very dull and flickering.**Minor** Offside Front Obligatory mirror slightly loose mirror glass. (3.3 (b) (i))

**MOT #7** 2020-03-18 12:58**MOT test number** 157515060266**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #6** 2019-03-15 14:36**MOT test number** 642452995835**Result** ✓ Passed**MOT #5** 2019-03-12 14:51**MOT test number** 618006097638**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre on 2mm and uneven wear on edges (5.2.3 (e))**MOT #4** 2018-03-12 12:46**MOT test number** 515068882791**Result** ✓ Passed**Advice** Smoke reading below 0.00 no print out available**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #3** 2017-03-14 17:28**MOT test number** 353796762664**Result** ✓ Passed



MOT #22017-03-07 12:20

MOT test number601890082352

ResultX Failed

AdviceSupplementary Restraint System warning lamp does not illuminate (5.4.2)

FailOffside Front Anti-lock braking system wiring excessively damaged (3.4.3)

FailNearside Front Brake hose excessively chafed (3.6.B.4d)

FailAnti-lock braking system warning lamp does not illuminate (3.4.1b)

FailNearside Front Brake hose has insufficient room to move, resulting in fouling on any part (3.6.B.4a)

MOT #12016-01-27 09:55

MOT test number468969272296

Result✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
25 April 2025

Tax status	Valid until 1 August
-------------------	----------------------

Days left	95
------------------	----

MOT expiry date	25 April 2025
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	DU12VWE
Plate since	2019-06-29
Current registration	DU12VWE
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-13
Last registration	2024-04-22
Complete history	See info



Registration #1	2012-03-13	26 mi
Registration #2	2016-01-27	36.374 mi
Registration #3	2017-03-07	42.332 mi
Registration #4	2017-03-14	42.374 mi
Registration #5	2018-03-12	46.433 mi
Registration #6	2019-03-12	52.440 mi
Registration #7	2019-03-15	52.449 mi
Registration #8	2020-03-18	56.993 mi
Registration #9	2020-03-20	56.993 mi
Registration #10	2020-03-20	56.993 mi
Registration #11	2020-03-20	56.993 mi
Registration #12	2020-03-20	56.993 mi
Registration #13	2020-03-20	56.993 mi
Registration #14	2020-03-20	56.993 mi
Registration #15	2020-03-20	56.993 mi
Registration #16	2020-03-20	56.993 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	1990 mm
Length	4892 mm
Kerb weight	1851 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3

Number of axles

2

Engine number

CAA 165224