



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	White
Year of manufacture	2011
Top speed	120 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-28
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	27
Total items failed	4

MOT #12	2023-11-07 11:22
MOT test number	922349718353
Result	✓ Passed
Next expiry date	2024-11-08
Advice	Slight under vehicle corrosion
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge Edge (5.2.3 (e))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #11	2022-11-09 15:33
MOT test number	694139294078
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2021-09-14 12:58

**MOT test number**

782352924835

**Result**

✓ Passed

**Advice** Rear Coil spring corroded Both rear springs corroded. (5.3.1 (b) (i))**Advice** Offside Play in steering rack inner joint(s)**Advice** Registration plate deteriorated but not likely to be misread Front and rear number plates. (0.1 (b))**MOT #9**

2020-08-05 15:12

**MOT test number**

716532179063

**Result**

✓ Passed

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #8**

2020-08-05 07:51

**MOT test number**

679561142975

**Result**

✗ Failed

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #7** 2019-08-14 14:52**MOT test number** 177452219262**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #6** 2019-08-13 07:50**MOT test number** 362258609401**Result** ✗ Failed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #5** 2018-08-01 11:11**MOT test number** 572357537103**Result** ✓ Passed**MOT #4** 2017-07-26 13:58**MOT test number** 928817063574**Result** ✓ Passed**Advice** Oil leak engine**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #3	2016-08-02 08:23
MOT test number	624382636709
Result	✓ Passed
Advice	Offside Rear Trailing arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Items removed from driver's view prior to test

MOT #2	2015-07-29 16:41
MOT test number	867590315248
Result	✓ Passed

MOT #1	2014-08-20 14:36
MOT test number	476982734268
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
8 November 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	8 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>BP61SGV</b>
Plate since	2019-03-29
Current registration	<b>BP61SGV</b>
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-28
Last registration	2023-11-07
Complete history	<a href="#">See info</a>



Registration #1	2011-09-28	8 mi
Registration #2	2014-08-20	25.940 mi
Registration #3	2015-07-29	35.084 mi
Registration #4	2016-08-02	45.664 mi
Registration #5	2017-07-26	54.885 mi
Registration #6	2018-08-01	64.496 mi
Registration #7	2019-08-13	73.746 mi
Registration #8	2020-08-20	83.000 mi
Registration #9	2021-08-20	92.250 mi
Registration #10	2022-08-20	101.500 mi
Registration #11	2023-08-20	110.750 mi
Registration #12	2024-08-20	120.000 mi
Registration #13	2025-08-20	129.250 mi
Registration #14	2026-08-20	138.500 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	BJ67398
---------------	---------