



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Black
Year of manufacture	2007
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 3.200 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-06-24
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-22
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	30
Total items failed	19

MOT #21 2023-08-23 18:10

MOT test number 977683727064

Result ✓ Passed

Next expiry date 2024-08-22

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both sides rear (5.3.4 (a) (i))

**Advice** Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))

MOT #20 2022-08-17 14:35

MOT test number 183267589186

Result ✓ Passed

**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #19** 2022-08-17 14:35**MOT test number** 229835639443**Result** ✗ Failed**Pass with rectification** Stop lamp(s) all not working (4.3.1 (a) (iii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #18** 2021-06-23 13:35**MOT test number** 972062411646**Result** ✓ Passed**MOT #17** 2021-06-22 14:58**MOT test number** 758671092708**Result** ✗ Failed**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #16** 2020-06-27 11:03**MOT test number** 350765594105**Result** ✓ Passed**MOT #15** 2019-06-26 10:14**MOT test number** 611205422487**Result** ✓ Passed**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #14** 2018-06-30 11:03**MOT test number** 366711981411**Result** ✓ Passed**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #13** 2018-06-30 09:57**MOT test number** 176525785112**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Offside Front Position lamp light intensity significantly reduced dull (4.2.3 (a) (ii))**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #12** 2017-06-12 09:41**MOT test number** 493650760297**Result** ✓ Passed**Advice** Offside Front tyre wearing on inner edge**MOT #11** 2017-02-23 12:21**MOT test number** 362121565081**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Engine oil level low

**MOT #10** 2015-12-29 13:04**MOT test number** 578035234892**Result** ✓ Passed**MOT #9** 2015-01-02 14:45**MOT test number** 225532005022**Result** ✓ Passed**MOT #8** 2015-01-02 14:45**MOT test number** 557562505073**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #7** 2013-07-22 13:41**MOT test number** 338173503476**Result** ✓ Passed**Notice** Collant system /radiator cap missing**MOT #6** 2013-07-22 11:00**MOT test number** 858703103205**Result** ✗ Failed**Notice** Collant system /radiator cap missing**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #5	2012-07-09 11:12
MOT test number	388691792137
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Coolant leak

MOT #4	2012-07-05 17:14
MOT test number	338037182162
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Stop lamp not working (1.2.1b)
Notice	Coolant leak
Pass with rectification	Nearside Headlamp aim too low (1.8)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Centre Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)
Fail	Nearside Stop lamp not working (1.2.1b)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #3	2012-06-07 12:28
MOT test number	217749252429
Result	✗ Failed
Fail	Centre Rear Seat belt has a cut which has significantly weakened the webbing (5.2.2a)
Fail	Front Body has a sharp edge caused by damage (6.1.C.1)
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Fail	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Front Headlamp insecure (1.7.3)
Fail	Front registration plate missing (6.3.1a)
Advice	Nearside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

MOT #2	2011-05-13 15:26
MOT test number	329323631118
Result	✓ Passed

MOT #1	2010-05-17 17:53
MOT test number	630827330110
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
22 August 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	22 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-16
Last registration	2023-08-23
Complete history	<a href="#">See info</a>



Registration #1	2007-06-16	20 mi
Registration #2	2010-05-17	29.516 mi
Registration #3	2011-05-13	36.799 mi
Registration #4	2012-06-07	41.812 mi
Registration #5	2012-07-05	41.832 mi
Registration #6	2012-07-09	41.832 mi
Registration #7	2013-07-22	47.813 mi
Registration #8	2013-07-22	47.813 mi
Registration #9	2015-01-02	55.839 mi
Registration #10	2015-12-29	60.758 mi
Registration #11	2017-02-23	66.894 mi
Registration #12	2018-05-29	71.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2020-05-29	79.277 mi
Registration #15	2021-05-29	83.277 mi
Registration #16	2022-05-29	87.277 mi
Registration #17	2023-05-29	91.277 mi
Registration #18	2024-05-29	95.277 mi
Registration #19	2025-05-29	99.277 mi
Registration #20	2026-05-29	103.277 mi
Registration #21	2027-05-29	107.277 mi
Registration #22	2028-05-29	111.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1055 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

G4EE7705908