





report date: 2024-03-29

#### General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI STARTLINE
Colour	Black
Year of manufacture	2016
Top speed	107 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2022-04-09

Pictures 23

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT I	nistory
-------	---------

MOT expiry date	2025-04-24
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	10
Total items failed	8

MOT #7	2024-04-19 09:14
MOT test number	598968795910
Result	✓ Passed
Next expiry date	2025-04-24
Advice Oil leak, but not excessive engine (8.4.1 (a) (i))	

MOT #6	2023-04-24 14:44
MOT test number	863772326064
Result	<b>✓</b> Passed
MOT #5	2022-04-25 16:39
MOT test number	131019393538
Result	✓ Passed
MOT #4	2021-04-01 08:37

	·
MOT #4	2021-04-01 08:3
MOT test	number 66294046971
Result	✓ Passe
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

CarCheck.co.uk page 3/11



**Pass with rectification** 

Advice

**GF66CEN** 

report date: 2024-03-29

MOT test number

Result

Pass with rectification

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor

(b) (i))

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

MOT test number

Result

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #1** 2019-11-12 16:57 **MOT** test number 136326702482 Result × Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii)) Fail Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Fail Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	24 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



report date: 2024-03-29


#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	

Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

Owner mistory	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIX
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-10-18
Last registration	2024-04-19
Complete history	See info



Registration #1	2016-10-18	29 mi
Registration #2	2019-11-12	45.064 mi
Registration #3	2019-11-14	45.064 mi
Registration #4	2021-04-01	65.478 mi
Registration #5	2021-04-01	65.478 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 66
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



## Dimensions & weight

Width	2065 mm
Height	1823 mm
Length	4408 mm
Wheel base	2682 mm
Kerb weight	1472 kg
Max. allowed weight	2141 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
CarChock co.uk	pago 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	DFSD080105