



report date: 2024-03-29

General information

Make	KIA
Model	SEDONA CRDI L
Colour	Blue
Year of manufacture	2005
Top speed	110 mph
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	310 Nm at 2.000 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.5 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-12
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-23
MOT pass rate	62 %
MOT passed	16
Failed MOT tests	10
Total advice items	22
Total items failed	21

MOT #26	2024-03-20 16:18
MOT test number	643103239906
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Offside Front side repeater cover missing

MOT #25	2024-03-20 09:49
MOT test number	670220507245
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Front side repeater cover missing
Fail	Offside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #24**

2023-03-17 09:25

**MOT test number**

840190692065

**Result**

✓ Passed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 215/65/15 (5.2.3 (e))

**Advice** Offside Front side repeater cover missing

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))

**MOT #23**

2022-03-22 10:49

**MOT test number**

132326067437

**Result**

✓ Passed

**Advice** Offside Front side repeater damaged

**Advice** Offside sill corroded

**MOT #22**

2022-03-22 10:49

**MOT test number**

166789207671

**Result**

✗ Failed

**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Offside Front side repeater damaged

**Advice** Offside sill corroded

**MOT #21**

2021-03-24 11:57

**MOT test number**

879238063400

**Result**

✓ Passed

**Advice** Offside Rear Outer Seat belt anchorage prescribed area is corroded but not considered excessive outer sill (7.1.1 (a) (ii))



<b>MOT #20</b>	2019-12-19 13:57
<b>MOT test number</b>	772150495833
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

<b>MOT #19</b>	2019-12-12 11:59
<b>MOT test number</b>	408697750408
<b>Result</b>	✗ Failed
<b>Minor</b>	Offside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
<b>Fail</b>	Offside Rear Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
<b>Fail</b>	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

<b>MOT #18</b>	2019-09-10 15:48
<b>MOT test number</b>	595050132651
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt outer (6.1.7 (g) (ii))
<b>Fail</b>	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt outer (6.1.7 (g) (ii))
<b>Minor</b>	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Fail</b>	Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

<b>MOT #17</b>	2018-09-26 09:24
<b>MOT test number</b>	980189093768
<b>Result</b>	✓ Passed

<b>MOT #16</b>	2017-07-03 12:15
<b>MOT test number</b>	814363163104
<b>Result</b>	✓ Passed

**MOT #15** 2016-07-07 16:46**MOT test number** 198690380819**Result** ✓ Passed**MOT #14** 2016-07-04 09:09**MOT test number** 989519656550**Result** ✗ Failed**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Emissions not tested emissions not tested due to major leak of exhaust gases (7.4.B.1)**Fail** Exhaust has a major leak of exhaust gases back box (7.1.2)**MOT #13** 2015-07-04 11:38**MOT test number** 888405785164**Result** ✓ Passed**Notice** O/s/r tyre starting to crack and perish**MOT #12** 2015-07-04 11:38**MOT test number** 439375385100**Result** ✗ Failed**Notice** O/s/r tyre starting to crack and perish**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #11** 2014-06-26 11:15**MOT test number** 307717574159**Result** ✓ Passed



MOT #10	2014-06-26 11:15
MOT test number	765017874197
Result	✗ Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #9	2013-06-18 15:09
MOT test number	439579163193
Result	✓ Passed

MOT #8	2013-06-17 17:43
MOT test number	147278063165
Result	✗ Failed
Fail	Exhaust system not adequately supported (7.1.1)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #7	2012-07-02 17:19
MOT test number	809894882156
Result	✓ Passed
Notice	Engine mounting collapsed o/s/f

MOT #6	2012-07-02 16:06
MOT test number	297964982170
Result	✗ Failed
Notice	Engine mounting collapsed o/s/f
Fail	Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
Fail	Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #5** 2011-06-25 11:20**MOT test number** 739736071171**Result** ✓ Passed**MOT #4** 2011-06-25 10:52**MOT test number** 288246771177**Result** ✗ Failed**Fail** Centre Exhaust system not adequately supported (7.1.1)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2010-07-21 10:13**MOT test number** 854422400216**Result** ✓ Passed**Notice** O/S/F TYRE INNER EDGE WEARING**MOT #2** 2009-03-05 10:39**MOT test number** 981374069043**Result** ✓ Passed**MOT #1** 2008-05-08 10:45**MOT test number** 343279428183**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)





Tax & MOT check

X

Untaxed

Tax expired:  
1 October 2022

✓

MOT

Expires:  
23 March 2025

Tax status	Expired at 1 October 2022
Days left	576 days too late
MOT expiry date	23 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>MF05YTO</b>
Plate since	2019-03-29
Current registration	<b>MF05YTO</b>
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-05-13
Last registration	2024-03-20
Complete history	<a href="#">See info</a>



Registration #1	2005-05-13	13 mi
Registration #2	2008-05-08	21.143 mi
Registration #3	2009-03-05	25.615 mi
Registration #4	2010-07-21	28.815 mi
Registration #5	2011-06-25	34.532 mi
Registration #6	2011-06-25	34.532 mi
Registration #7	2012-07-02	40.189 mi
Registration #8	2012-07-02	40.189 mi
Registration #9	2013-06-17	44.627 mi
Registration #10	2013-06-18	44.627 mi
Registration #11	2014-06-26	49.187 mi
Registration #12	2015-07-04	54.093 mi
Registration #13	2016-07-04	58.148 mi
Registration #14	2016-07-04	58.148 mi
Registration #15	2016-07-04	58.148 mi
Registration #16	2016-07-04	58.148 mi
Registration #17	2016-07-04	58.148 mi
Registration #18	2016-07-04	58.148 mi
Registration #19	2016-07-04	58.148 mi
Registration #20	2016-07-04	58.148 mi
Registration #21	2016-07-04	58.148 mi
Registration #22	2016-07-04	58.148 mi
Registration #23	2016-07-04	58.148 mi
Registration #24	2016-07-04	58.148 mi
Registration #25	2016-07-04	58.148 mi
Registration #26	2016-07-04	58.148 mi

**More info** >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2184 mm
Height	1735 mm
Length	4890 mm
Wheel base	2905 mm
Kerb weight	2220 kg
Max. allowed weight	2738 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7



<b>Number of axles</b>	2
<b>Engine number</b>	J3678197