





| General information | |
|---------------------|---|
| Make | VOLKSWAGEN |
| Model | BEETLE SPORT TDI BLUEMOTION TECHNOLOGY DSG |
| Colour | Blue |
| Year of manufacture | 2016 |
| Top speed | 124 mph |
| Gearbox | 6 speed Semi Auto |

Engine & fuel consumption

| Power | 148 BHP |
|-------------------------|---------------------|
| Max. torque | 340 Nm at 1.750 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 58.9 mpg |
| CO2 emission | 124 g/km |
| CO2 label | D |





KV66AAO report date: 2024-03-29

Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2022-09-15 |
| Pictures | 31 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

4

2022-01-03

sting price





source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-09-13 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 2 |
| Total items failed | 6 |

| MOT #8 | 2023-09-14 09:18 |
|--|------------------|
| MOT test number | 327139643534 |
| Result | 🗸 Passed |
| Next expiry date | 2024-09-13 |
| Advice Emissions too low for a reading | |

| MOT #7 | | 2023-09-13 09:27 |
|---|---|------------------|
| MOT test number | | 642274764149 |
| Result | | 🗙 Failed |
| Pass with rectification | Nearside Headlamp aim too low (4.1.2 (a)) | |
| Fail Nearside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i)) | | |
| Pass with rectification | Offside Headlamp aim too low (4.1.2 (a)) | |
| Advice Emissions too low for a reading | | |
| Fail Offside Rear Rear fog lamp not working (4.5.1 (a) (ii)) | | |

| МОТ #6 | 2022-09-14 13:54 |
|-----------------|------------------|
| MOT test number | 259913548763 |
| Result | ✓ Passed |



| MOT #5 | 2022-09-14 06:42 |
|---|----------------------------|
| MOT test number | 676081238818 |
| Result | 🗙 Failed |
| Fail Brake pedal has insufficient reserve travel (1.1.2 (a)) | |
| Fail Offside Front Track rod end ball joint dust cover insecure so that it no long dirt (2.1.3 (g) (ii)) | er prevents the ingress of |
| МОТ #4 | 2022-03-09 16:07 |
| MOT test number | 821400331747 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2021-09-07 10:04 |
| MOT test number | 198323270030 |

Result

| 603800323856 |
|--------------|
| ✓ Passed |
| |

| MOT #1 | 2019-09-05 08:14 |
|-----------------|------------------|
| MOT test number | 955004932791 |
| Result | ✓ Passed |

🗸 Passed

KV66AAO

report date: 2024-03-29



Tax & MOT check

| Taxed Tax due: 1 September 2024 | ✓ MOT Expires: 13 September 2024 |
|---|---|
| Tax status | Valid until 1 September |
| Days left | 124 |
| MOT expiry date | 13 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------|
| Date | FETTOR |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Date | OLE . |
| Category | AM |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| ******** | |
| | |
| and the second sec | |
| *********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2016-09-08 |
| Last registration | 2023-09-14 |
| Complete history | See info |



| Registration #1 | 2016-09-08 | 18 mi |
|------------------------------------|------------|--|
| Registration #2 | 2019-09-05 | 22.434 mi |
| Registration #3 | 2020-09-02 | 30.155 mi |
| Registration #4 | 2021-09-07 | 42.814 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | 2022-03-09 | 47.568 mi |
| | | |
| Registration #7 | | 11.777 est |
| Registration #7 Registration #8 | | 11.777 es |
| - | | 01,000 est 01,000 est 01,000 est |
| Registration #8 | | 00,000 est 01,000 est 00,000 est 01,000 est |

More info \rightarrow





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 90% |
| Pedestrian | 53% |
| Safety systems | 86% |
| Overall rating | 83% |
| Video | see crash video |



| Dimensions & weight | |
|------------------------|------------------|
| Width | 2021 mm |
| Height | 1486 mm |
| Length | 4278 mm |
| Wheel base | 2537 mm |
| Kerb weight | 1445 kg |
| Max. allowed weight | 1900 kg |
| Additional information | |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 4 |

| Number of axles | 2 |
|-----------------|------------|
| Engine number | CUUB142074 |