



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	HILUX 4X4 D-4D D/C INVINCIBLE
Colour	Silver
Year of manufacture	2008
Top speed	108 mph
0 - 60 mph	11.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	169 BHP
Max. torque	343 Nm at 1.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	35.3 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-26
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-09-18
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	8
Total items failed	4

MOT #13	2020-09-10 15:57
MOT test number	997899004641
Result	✓ Passed
Next expiry date	2021-09-18

MOT #12	2019-09-19 15:19
MOT test number	774057818670
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2018-09-15 09:20
MOT test number	462747043160
Result	✓ Passed

MOT #10	2018-09-07 15:24
MOT test number	785891188775
Result	✗ Failed
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #9	2017-09-12 15:37
MOT test number	449001069030
Result	✓ Passed

**MOT #8** 2017-09-11 13:30**MOT test number** 170353511385**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #7** 2016-09-12 08:53**MOT test number** 173215933219**Result** ✓ Passed**MOT #6** 2015-08-27 13:21**MOT test number** 306095685871**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2014-08-27 09:29**MOT test number** 526709434239**Result** ✓ Passed**MOT #4** 2013-09-12 14:02**MOT test number** 358155653250**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #3 2013-09-12 14:02

MOT test number 388355253255

Result ✗ Failed

Pass with rectification Offside Front Headlamp aim too low (1.8)

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Pass with rectification Nearside Front Headlamp aim too low (1.8)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #2 2012-09-04 10:21

MOT test number 227778742228

Result ✓ Passed

MOT #1 2011-08-31 11:06

MOT test number 757433641268

Result ✓ Passed

Notice Front wipers smearing screen but still giving an adequate view of the road

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)



Tax & MOT check

✕
Untaxed

Tax expired:
19 May 2021

✕
MOT

Expired:
18 September 2021

Tax status

Expired at 19 May 2021

Days left

1076 days too late

MOT expiry date

18 September 2021

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-09-12
Last registration	2020-09-10
Complete history	See info



Registration #1	2008-09-12	22 mi
Registration #2	2011-08-31	72.486 mi
Registration #3	2012-09-04	77.358 mi
Registration #4	2013-09-12	81.260 mi
Registration #5	2014-08-27	86.332 mi
Registration #6	2015-08-27	92.561 mi
Registration #7	2016-09-12	102.820 mi
Registration #8	2017-09-12	113.079 mi
Registration #9	2018-09-12	123.338 mi
Registration #10	2019-09-12	133.597 mi
Registration #11	2020-09-10	143.856 mi
Registration #12	2021-09-10	154.115 mi
Registration #13	2022-09-10	164.374 mi
Registration #14	2023-09-10	174.633 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1835 mm
Height	1810 mm
Length	5255 mm
Wheel base	3085 mm
Kerb weight	1885 kg
Max. allowed weight	2940 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1KD7580842