



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI 115 SWB P/V
Colour	Silver
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-18
Pictures	39
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-30
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	37
Total items failed	10

MOT #15	2023-05-23 14:57
MOT test number	654783073267
Result	✓ Passed
Next expiry date	2024-05-30
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Engine oil leak
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14**

2023-05-23 08:58

MOT test number

811127227797

Result**✗ Failed**

Fail Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Engine oil leak

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #13

2022-05-31 13:29

MOT test number

397609599865

Result**✓ Passed**

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #12

2021-07-14 16:54

MOT test number

196485635900

Result**✓ Passed**

Advice Brake pipe corroded, covered in grease or other material nearside to offside rear brake pipe corroded (1.1.11 (c))

Advice Oil leak, but not excessive engine oil leak (8.4.1 (a) (i))

**MOT #11**

2021-07-13 14:51

MOT test number

511153319454

Result**✗ Failed**

- Advice** Oil leak, but not excessive engine oil leak (8.4.1 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Bonnet cannot be secured in the closed position (3.1 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material nearside to offside rear brake pipe corroded (1.1.11 (c))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #10

2020-07-18 14:28

MOT test number

395233757570

Result**✓ Passed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak attention advised
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #9**

2020-07-18 08:15

MOT test number

714809636251

Result

✗ Failed

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Front Lower Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
- Advice** Oil leak attention advised
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #8

2019-04-13 09:46

MOT test number

874767851593

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material centre (1.1.11 (c))

MOT #7

2018-04-20 09:30

MOT test number

523576845799

Result

✓ Passed

- Advice** Offside Front abs wiring insecure but not chafing
- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Both rear tyres perishing
- Advice** Oil leak

**MOT #6** 2017-04-26 08:42**MOT test number** 121206081647**Result** ✓ Passed

Advice Offside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #5 2016-04-13 07:13**MOT test number** 385402275172**Result** ✓ Passed**MOT #4** 2015-04-25 13:02**MOT test number** 657765315115**Result** ✓ Passed**MOT #3** 2014-04-26 09:17**MOT test number** 838876614173**Result** ✓ Passed**MOT #2** 2013-04-24 16:51**MOT test number** 319234513108**Result** ✓ Passed**MOT #1** 2011-07-16 09:52**MOT test number** 545867891162**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
30 May 2024

Tax status		Valid until 1 November
Days left		185
MOT expiry date		30 May 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-25
Last registration	2023-05-23
Complete history	See info



Registration #1	2010-05-25	7 mi
Registration #2	2011-07-16	18.404 mi
Registration #3	2013-04-24	36.704 mi
Registration #4	2014-04-26	43.379 mi
Registration #5	2015-04-25	49.705 mi
Registration #6	2016-04-13	50.074 mi
Registration #7	2017-04-26	58.219 mi
Registration #8	2018-04-20	60.880 mi
Registration #9	2019-04-13	62.192 mi
Registration #10	2020-05-23	65.277 mi
Registration #11	2021-05-23	65.277 mi
Registration #12	2022-05-23	65.277 mi
Registration #13	2023-05-23	65.277 mi
Registration #14	2024-05-23	65.277 mi
Registration #15	2025-05-23	65.277 mi
Registration #16	2026-05-23	65.277 mi
Registration #17	2027-05-23	65.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Height	1944 mm
Length	4782 mm
Kerb weight	1678 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	C053829