



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI S 5STR
Colour	Blue
Year of manufacture	2005
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-04
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2021-12-25
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	54
Total items failed	14

MOT #19	2020-12-23 13:41
----------------	------------------

MOT test number	738670032321
------------------------	--------------

Result	✓ Passed
---------------	----------

Next expiry date	2021-12-25
-------------------------	------------

- Advice** Offside Rear Shock absorbers has a slightly worn bush top mount (5.3.2 (c))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush top mount (5.3.2 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #18**

2020-12-23 09:38

MOT test number

404282076249

Result**✗ Failed**

- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush top mount (5.3.2 (c))
- Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush top mount (5.3.2 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #17

2019-05-28 08:24

MOT test number

613237463975

Result**✓ Passed**

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2019-05-23 08:57

MOT test number

970305758103

Result**✗ Failed**

- Fail** Nearside Position lamp not working (4.2.1 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #15** 2018-06-26 14:24**MOT test number** 604140317398**Result** ✓ Passed**Advice** Offside Rear tyre stepping on inner edge**Advice** Rear inner brake pads appear to be worn**MOT #14** 2018-06-26 09:28**MOT test number** 503052098855**Result** ✗ Failed**Advice** Offside Rear tyre stepping on inner edge**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear inner brake pads appear to be worn**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #13** 2017-06-23 12:13**MOT test number** 904037231616**Result** ✓ Passed**Advice** Service light on**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Undertrays fitted**Advice** O/s rear handbrake effort slightly low**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** N/s rear shock dust cover adrift

**MOT #12**

2017-06-19 10:44

MOT test number

995075296947

Result**✗ Failed****Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** N/s rear shock dust cover adrift**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Advice** Eml on**Advice** O/s rear handbrake effort slightly low**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** O/s rear brake binding slightly**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Service light on**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Undertrays fitted**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #11**

2016-06-06 13:17

MOT test number

443107818684

Result**✓ Passed****Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #10** 2016-06-06 08:57**MOT test number** 959632136022**Result** ✗ Failed**Advice** Nearside Front Inner brake pad worn**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Offside Rear brake disc has a big score mark and grinding when brake applied , advise brake check**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #9** 2014-12-31 10:13**MOT test number** 765805764363**Result** ✓ Passed**MOT #8** 2013-12-30 14:40**MOT test number** 309234763308**Result** ✓ Passed**MOT #7** 2012-12-31 10:47**MOT test number** 317716962390**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-01-04 16:59**MOT test number** 897144102028**Result** ✓ Passed

**MOT #5** 2011-04-08 14:45**MOT test number** 108958191051**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4 2010-03-25 10:48**MOT test number** 720504880017**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2009-03-25 11:06**MOT test number** 604444289010**Result** ✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Lower Suspension component mounting prescribed area is distorted but not considered excessive (2.4.A.3)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

MOT #2 2008-03-27 15:07**MOT test number** 662047988051**Result** ✓ Passed

Advice Offside Seat belt anchorage prescribed area is distorted but not considered excessive (5.2.6)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #12008-03-27 15:07

MOT test number932297588012

Result

Failed

- Pass with rectification

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Pass with rectification

Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice

Offside Seat belt anchorage prescribed area is distorted but not considered excessive (5.2.6)
- Pass with rectification

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
6 October 2021

X

MOT

Expired:
25 December 2021

Tax status	Expired at 6 October 2021
Days left	935 days too late
MOT expiry date	25 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-04-02
Last registration	2020-12-23
Complete history	See info



Registration #1	2005-04-02	18 mi
Registration #2	2008-03-27	30.113 mi
Registration #3	2009-03-25	39.098 mi
Registration #4	2010-03-25	40.861 mi
Registration #5	2011-04-08	61.956 mi
Registration #6	2012-01-04	69.826 mi
Registration #7	2012-12-31	75.203 mi
Registration #8	2013-12-30	78.888 mi
Registration #9	2014-12-31	82.507 mi
Registration #10	2016-06-06	92.276 mi
Registration #11	2016-06-06	92.276 mi
Registration #12	2016-06-06	92.276 mi
Registration #13	2016-06-06	92.276 mi
Registration #14	2016-06-06	92.276 mi
Registration #15	2016-06-06	92.276 mi
Registration #16	2016-06-06	92.276 mi
Registration #17	2016-06-06	92.276 mi
Registration #18	2016-06-06	92.276 mi
Registration #19	2016-06-06	92.276 mi
Registration #20	2016-06-06	92.276 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKC 732958