





report date: 2024-03-29

### General information

Make	AUDI
Model	A1 TDI S LINE
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	105 BHP	
Max. torque	250 Nm at 2.500 rpm	
Engine capacity	1.598 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	60.1 mpg	
Consumption extra urban	78.5 mpg	
Consumption combined	70.6 mpg	
CO2 emission	105 g/km	
CO2 label	В	



CarCheck.co.uk page 1/13



## Internet history

### Entry 1

Date 2021-06-12

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-06
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	20
Total items failed	7

MOT #14		2023-06-07 13:12
MOT test	number	252365304525
Result		✓ Passed
Next expiry date 2024-06-0		2024-06-06
Advice	Nearside Rear Tyre slightly damaged Outer side wall (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged Outer side wall (5.2.3 (d) (ii))	

MOT #13		20	23-06-07 13:12
MOT test i	number		917207453172
Result			🗙 Failed
Advice Nearside Rear Tyre slightly damaged Outer side wall (5.2.3 (d) (ii))			
Advice Nearside Front Tyre slightly damaged Outer side wall (5.2.3 (d) (ii))			
Pass wit	h rectification	Nearside Headlamp aim too low and too far to the left. (4.1.2 (a))	

CarCheck.co.uk page 3/13



**MOT #12** 2023-05-24 10:50

**MOT test number** 972849681350

Result × Failed

Fail Front Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))

**Fail** Exhaust has a major leak of exhaust gases Flexible pipe (6.1.2 (a))

Advice Nearside Front Tyre slightly damaged Outer side wall (5.2.3 (d) (ii))

**Fail** Nearside Headlamp levelling device inoperative (4.1.5 (a))

Fail Offside Rear Position lamp light intensity significantly reduced (4.2.3 (a) (ii))

Advice Nearside Rear Tyre slightly damaged Outer side wall (5.2.3 (d) (ii))

MOT #11 2022-05-31 14:28

**MOT test number** 228176638982

**Result** ✓ Passed

MOT #10 2022-05-31 13:28

**MOT test number** 541501436072

Result X Failed

Fail Nearside Headlamp insecure (4.1.1 (c))

MOT #9 2021-05-29 13:33

MOT test number 442536032081

**Advice** Undertrays fitted

CarCheck.co.uk page 4/13



MOT #8 2020-07-10 07:55

**MOT test number** 587162734096

Result \sqrt{Passed}

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

MOT #7 2019-07-03 10:07

**MOT test number** 380503225879

Result 

Passed

**Advice** Exhaust Corroded - Double Skinned

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened s (1.1.14 (a) (ii))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened s (1.1.14 (a) (ii))

MOT #6 2018-06-25 09:45

MOT test number 390488585064

**Result** ✓ Passed

**MOT #5** 2017-06-29 09:05

MOT test number 197262568615

Result 

Passed

CarCheck.co.uk page 5/13



**MOT #4** 2017-06-29 07:59

MOT test number 563407908611

Result X Failed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #3 2016-06-16 12:05

MOT test number 138602079633

Result \( \sqrt{Passed} \)

MOT #2 2015-06-12 12:08

**MOT test number** 535833465192

**Notice** Under-trays fitted obscuring some underside components

**MOT #1** 2014-06-12 11:33

**MOT test number** 708243564155

**Result** ✓ Passed

CarCheck.co.uk page 6/13



### Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	6 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra AUDI salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



### Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	AIR.
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-06-17
Last registration	2023-06-07
Complete history	See info



Registration #1	2011-06-17	11 mi
Registration #2	2014-06-12	26.841 mi
Registration #3	2015-06-12	34.545 mi
Registration #4	2016-06-16	40.326 mi
Registration #5	2017-06-29	47.073 mi
Registration #6	2017-06-29	47.079 mi
Registration #7	2018-06-25	55.742 mi
Registration #8	2019-07-03	63.268 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PR P. P. P.

More info >

77. 777 mg

CarCheck.co.uk page 12/13



### Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	79%
Pedestrian	49%
Safety systems	86%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1740 mm
Height	1416 mm
Length	3954 mm
Wheel base	2469 mm
Kerb weight	1140 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 13/13

**Engine number** 

CAYA43257