



report date: 2024-03-28

General information

Make	MINI
Model	COUNTRYMAN ONE ONE
Colour	Blue
Year of manufacture	2011
Top speed	107 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-02
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-06
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	17
Total items failed	4

MOT #11	2023-06-27 15:28
---------	------------------

MOT test number	998660895987
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-06
------------------	------------

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D Bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Slightly worn on outer edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2023-06-27 08:21

MOT test number

792960764431

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Valve stem seriously damaged (5.2.3 (j))**Fail** Offside Front Valve stem seriously damaged (5.2.3 (j))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D Bush (5.3.4 (a) (i))**Fail** Offside Rear Valve stem seriously damaged (5.2.3 (j))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9**

2022-06-28 08:11

MOT test number

866669413531

Result**✓ Passed****Advice** Nearside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn very close to the limit 205/60/16 (5.2.3 (e))**MOT #8**

2021-07-07 12:56

MOT test number

758517066539

Result**✓ Passed****MOT #7**

2020-10-10 13:24

MOT test number

519606522028

Result**✓ Passed**

**MOT #6** 2019-10-07 16:01**MOT test number** 912243137703**Result** ✓ Passed**MOT #5** 2018-10-15 12:07**MOT test number** 578929522410**Result** ✓ Passed**MOT #4** 2017-11-21 10:22**MOT test number** 649870534646**Result** ✓ Passed**MOT #3** 2016-11-17 10:07**MOT test number** 840648077497**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Cover missing of n/s mirror**MOT #2** 2015-11-16 12:23**MOT test number** 629036708003**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2014-10-06 09:53**MOT test number** 138389074223**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
6 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-09-05
Last registration	2023-06-27
Complete history	See info



Registration #1	2011-09-05	13 mi
Registration #2	2014-10-06	14.631 mi
Registration #3	2015-11-16	20.448 mi
Registration #4	2016-11-17	27.902 mi
Registration #5	2017-11-21	41.095 mi
Registration #6	2018-10-15	47.901 mi
Registration #7	2019-10-07	55.938 mi
Registration #8	2020-06-27	55.938 mi
Registration #9	2020-06-27	55.938 mi
Registration #10	2020-06-27	55.938 mi
Registration #11	2020-06-27	55.938 mi
Registration #12	2020-06-27	55.938 mi
Registration #13	2020-06-27	55.938 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	B412I993