





report date: 2024-03-29

General information

Make	CITROEN
Model	NEMO HDI STOP AND START
Colour	Grey
Year of manufacture	2012
Top speed	96 mph
0 - 60 mph	16.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



CY12FHF

report date: 2024-03-29

Internet history

Entry 1

Date 2022-03-09

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



✓ Passed

MOT history

Result

MOT expiry date	2024-11-21
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	5
Total items failed	7

MOT #14	2023-11-22 16:56
MOT test number	838050156110
Result	✓ Passed
Next expiry date	2024-11-21

MOT #	13	2023-11-07 12:17
MOT te	st number	496399933201
Result		× Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail	Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))	
Fail (d))	Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of a	ny colour (8.2.2.2

MOT #12	2022-11-10 11:23
MOT test number	962619149339
Result	✓ Passed
MOT #11	2022-03-11 12:17
MOT test number	129766745584

CarCheck.co.uk page 3/12



MOT #10 2021-09-03 10:46

MOT test number 452821072241

Result ✓ Passed

MOT #9 2020-10-08 16:00

MOT test number 107003943245

✓ Passed Result

Advice Offside Front mirror loose

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2019-09-27 08:12

MOT test number 419358596844

Result Passed

MOT #7 2019-09-26 08:53

MOT test number 471118706971

Result × Failed

Shock absorbers has an excessively worn bush both top mounting (5.3.2 (c)) Fail

Battery insecure and likely to cause a short circuit (4.13 (a) (ii)) Fail

MOT #6 2018-09-18 15:23

MOT test number 345577264797

✓ Passed

Advice Offside Steering system slightly rough strut top bearing (2.1.1 (a))

CarCheck.co.uk page 4/12



X Failed

MOT #5 2018-09-18 13:50

MOT test number 415685328417

Result × Failed

Advice Offside Steering system slightly rough strut top bearing (2.1.1 (a))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #4 2017-09-27 08:31

MOT test number 411059285896

Result ✓ Passed

MOT #3 2016-11-09 12:12

MOT test number 278035792591

Result \rightarrow Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2015-06-05 09:05

MOT test number 425666955189

Result \rightarrow Passed

MOT #1 2015-06-05 09:05

MOT test number 327026355188

32702033310

Pass with rectification Headlamp aim too high (1.8)

Result

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

*		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN
	More info	>
Plate changes See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	NK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-15
Last registration	2023-11-22
Complete history	See info



Registration #1	2012-05-15	22 mi
Registration #2	2015-06-05	16.462 mi
Registration #3	2016-11-09	24.094 mi
Registration #4	2017-09-27	28.615 mi
Registration #5	2018-09-18	35.272 mi
Registration #6	2018-09-18	35.272 mi
Registration #7	2019-09-26	42.885 mi
Registration #8	2019-09-27	42.885 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	***
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	see crash video



Dimensions & weight

Width	1684 mm
Height	1721 mm
Length	3864 mm
Wheel base	2513 mm
Kerb weight	1090 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	00013902952

CarCheck.co.uk page 12/12