





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI BLACK EDITION
Colour	Black
Year of manufacture	2017
Top speed	107 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date	2023-04-26
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 2

, -		
Date	2023-04-14	
Pictures	0	
Listing price	<u>View report</u>	

source: cargurus.co.uk

Entry 1

, -		
Date	2021-07-02	
Pictures	11	
Listing price	<u>View report</u>	









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-04-17
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	5
Total items failed	3

MOT #7	2023-04-18 07:02
MOT test number	158938689274
Result	✓ Passed
Next expiry date	2024-04-17

MOT #6		2023-04-18 07:02
MOT test number		615783298520
Result		X Failed
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))	

MOT #5	2022-11-09 08:52
MOT test	number 906128284048
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Right on legal limits (5.2.3 (e))
Advice Offside Front Tyre worn close to legal limit/worn on edge Right on legal limits (5.2.3 (e))	

MOT #4	2021-11-13 09:52
MOT test number	733803848916
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #3 2020-10-29 09:12

MOT test number 921673113362

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear discs have corrosion on outer face. (1.1.14 (a) (ii))

MOT #2 2020-10-27 11:27

MOT test number 890370117527

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear discs have corrosion on outer face. (1.1.14 (a) (ii))

Fail Front Body component damaged and likely to cause injury Front grille damaged and has sharp edges. (6.2.1 (a) (i))

MOT #1 2020-05-03 08:46

MOT test number 472238510033

Result \(\sqrt{Passed} \)

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	17 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	

Damage 2

Type

Date

Jaillage 2

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	AIR AIR
Plate since	
Current registration	AIS OK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-05-11
Last registration	2023-04-18
Complete history	See info



Registration #1	2017-05-11	20 mi
Registration #2	2020-10-27	34.564 mi
Registration #3	2020-10-29	34.565 mi
Registration #4		11.777 es
Registration #5	2021-11-13	37.611 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2065 mm
Height	1858 mm
Length	4408 mm
Kerb weight	1594 kg
Max. allowed weight	2045 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2

CarCheck.co.uk page 11/11

Engine number

DFSD098897