



report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC
Colour	White
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	63 kW / 86 HP / 123 BHP
Max. torque	159 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 2


Date	2023-12-13
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-11-01
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-13
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	12
Total items failed	6

MOT #9	2023-11-14 14:58
MOT test number	854796644025
Result	✓ Passed
Next expiry date	2024-11-13

MOT #8	2023-11-14 10:17
MOT test number	946890331384
Result	✗ Failed
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #7	2022-11-03 13:02
MOT test number	371157427379
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2021-11-10 08:13**MOT test number** 870618320179**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2021-11-07 12:03**MOT test number** 858791435523**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Brake pedal anti-slip provision missing (1.1.2 (c))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #4** 2021-01-29 14:36**MOT test number** 471354734970**Result** ✓ Passed**MOT #3** 2020-02-19 17:26**MOT test number** 223464884098**Result** ✓ Passed**MOT #2** 2019-04-10 08:28**MOT test number** 498462514764**Result** ✓ Passed



MOT #12019-04-08 14:31

MOT test number243011343456

ResultX Failed

- Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail

Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail

Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Minor

Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))
- Fail

Offside Rear Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
13 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	13 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>YD16YPM</b>
Plate since	2019-03-29
Current registration	<b>YD16YPM</b>
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-04-29
Last registration	2023-11-14
Complete history	<a href="#">See info</a>



Registration #1	2016-04-29	20 mi
Registration #2	2019-04-08	20.752 mi
Registration #3	2019-04-10	20.574 mi
Registration #4	2020-02-19	24.677 mi
Registration #5	2021-01-29	25.538 mi
Registration #6	2022-05-20	26.277 mi
Registration #7	2022-05-20	26.277 mi
Registration #8	2022-05-20	26.277 mi
Registration #9	2022-05-20	26.277 mi
Registration #10	2022-05-20	26.277 mi
Registration #11	2022-05-20	26.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	83%
Pedestrian	50%
Safety systems	71%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2067 mm
Height	1610 mm
Length	4380 mm
Wheel base	2850 mm
Kerb weight	1374 kg
Max. allowed weight	1860 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	FU19816
---------------	---------