



Mercedes-Benz

LXIOVDR

report date: 2024-03-29

General information

Make	MERCEDES
Model	VITO 109 CDI LONG P/V
Colour	White
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	95 BHP
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-27
Pictures	3
Listing price	View report



source: cargurus.co.uk





MOT history

MOT expiry date	2024-09-07
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	17
Total items failed	10

MOT #15	2023-09-08 13:56
MOT test number	392854235531
Result	✓ Passed
Next expiry date	2024-09-07
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2023-09-08 07:57
MOT test number	607343518843
Result	✗ Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #13	2022-09-06 11:17
MOT test number	480301178208
Result	✓ Passed
Minor	Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #12**

2022-09-06 09:41

MOT test number

768495051571

Result

✗ Failed

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #11**

2021-08-27 17:54

MOT test number

117283413064

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #10**

2020-09-30 12:15

MOT test number

652628219966

Result

✓ Passed

Advice Rear Tyre worn close to legal limit/worn on edge NS/OS (5.2.3 (e))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front Brake pad(s) wearing thin NS/OS (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively NS/OS (1.1.14 (a) (i))**MOT #9**

2019-03-28 15:50

MOT test number

705001497276

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #8** 2018-03-26 13:41**MOT test number** 684052928176**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2018-03-26 12:08**MOT test number** 366658671765**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2017-03-27 16:04**MOT test number** 378006980230**Result** ✓ Passed**MOT #5** 2016-03-02 07:41**MOT test number** 996860965165**Result** ✓ Passed**MOT #4** 2016-03-02 07:41**MOT test number** 883117801412**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2015-03-03 08:55**MOT test number** 239772465005**Result** ✓ Passed



MOT #2	2014-03-13 18:25
MOT test number	339732174098
Result	✓ Passed

MOT #1	2013-03-13 08:17
MOT test number	267282673021
Result	✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
7 September 2024

Tax status		Valid until 1 October
Days left		154
MOT expiry date		7 September 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-30
Last registration	2023-09-08
Complete history	See info



Registration #1	2010-03-30	22 mi
Registration #2	2013-03-13	23.726 mi
Registration #3	2014-03-13	30.066 mi
Registration #4	2015-03-03	34.746 mi
Registration #5	2016-03-02	42.150 mi
Registration #6	2016-03-02	42.150 mi
Registration #7	2017-03-27	51.175 mi
Registration #8	2018-03-26	63.677 mi
Registration #9	2018-03-26	63.677 mi
Registration #10	2019-03-26	75.277 mi
Registration #11	2019-03-26	75.277 mi
Registration #12	2019-03-26	75.277 mi
Registration #13	2019-03-26	75.277 mi
Registration #14	2019-03-26	75.277 mi
Registration #15	2019-03-26	75.277 mi
Registration #16	2019-03-26	75.277 mi
Registration #17	2019-03-26	75.277 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	64698051797731