





report date: 2024-03-29

### General information

Make	BMW
Model	120 118D SPORT
Colour	Black
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	141 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/12



DG10DVW report date: 2024-03-29

MOT history

MOT expiry date	2024-08-03
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	16
Total items failed	9

MOT #18	2023-08-04 10:26
MOT test number	922304537302
Result	✓ Passed
Next expiry date	2024-08-03

MOT #17	2022-08-03 09:16
MOT test number	102606131419
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2021-07-10 08:47
MOT test number	839680253585
Result	✓ Passed
MOT #15	2021-07-09 14:46
MOT test number	999651184514
Result	<b>X</b> Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT #14

MOT test number

479172761563

Result

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT test number

Result

Pass with rectification

Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Pass with rectification

Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

 MOT #12
 2019-06-08 11:12

 MOT test number
 479296840117

 Result
 ✓ Passed

MOT #11

MOT test number

935666250145

Result

Fail Offside Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9 2017-06-08 08:00

**MOT test number** 391151754509

**Result** ✓ Passed

MOT #8 2016-10-26 11:19

**MOT test number** 415275219721

**Result** 
✓ Passed

**Advice** Both rear tyres slightly cracking

**Advice** Offside front tyre slightly cracking + misshaped

**MOT #7** 2015-10-27 14:23

**MOT test number** 879813873882

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-10-26 11:39

MOT test number 884061693708

Result X Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2014-11-03 12:48

MOT test number 467897104376

Result 

Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Front Headlamp aim too high (1.8)

MOT #3 2013-11-06 14:34 **MOT** test number 408320713493 Result ✓ Passed MOT #2 2013-11-06 14:34 949320613384 **MOT test number** Result × Failed **Pass with rectification** Nearside Headlamp aim too high (1.8) **Pass with rectification** Offside Headlamp aim too high (1.8)

MOT #1		2013-02-04 12:41
MOT test	number	165235833035
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	
Notice	Offside front tyre worn on outter	

CarCheck.co.uk page 5/12



DG10DVW report date: 2024-03-29



Tax status	Valid until 1 June
Days left	33
MOT expiry date	3 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

<b>^</b> -		histor	-
- ( ) ( )	vnor	nistar	٦.
$\smile$	VIICI	пизсоп	·v

For how long did the current and previous owner(s) have this BMW? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	
***************************************	
HARMAN AND AND AND AND AND AND AND AND AND A	
**********	
THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Contract resistration	NE CONTRACTOR
	UK UK
Plate since	
	More info >
	Piore inio /

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-02
Last registration	2023-08-04
Complete history	See info



Registration #1	2010-03-02	23 mi
Registration #2	2013-02-04	25.910 mi
Registration #3	2013-11-06	32.764 mi
Registration #4	2014-11-03	39.060 mi
Registration #5	2015-10-26	43.846 mi
Registration #6	2015-10-27	43.846 mi
Registration #7	2016-10-26	46.838 mi
Registration #8	2017-06-08	50.030 mi
Registration #9	2018-06-06	56.184 mi
Registration #10		11.777 es
Registration #10 Registration #11		11.777 es
-		11.777 ea 11.777 ea
Registration #11		11,777 es 11,777 es 11,777 es
Registration #11 Registration #12		11,777-66 11,777-66 11,777-66 11,777-66
Registration #11 Registration #12 Registration #13		11,777-66 11,777-66 11,777-66 11,777-66
Registration #11 Registration #12 Registration #13 Registration #14		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1748 mm
Height	1421 mm
Length	4239 mm
Wheel base	2660 mm
Kerb weight	1345 kg
Max. allowed weight	1855 kg

### Additional information

Fuel tank capacity	51	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 86287337