



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AVENSIS D-4D TR
Colour	Silver
Year of manufacture	2007
Top speed	200 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	300 Nm at 2.400 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	146 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-15
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-10
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	32
Total items failed	12

MOT #20	2023-06-08 15:09
MOT test number	201725719547
Result	✓ Passed
Next expiry date	2024-06-10
Advice	Engine MIL: (malfunction indicator lamp) indicating a malfunction
Advice	Front Washers Working using Rear Washer Switch
Advice	VSC light (Vehicle Stability Control light) illuminated
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources 1 of 2 Working (4.7.1 (b) (i))
Advice	Front Run flat and conventional tyres mixed across the same axle.

MOT #19	2023-06-08 08:32
MOT test number	294890894850
Result	✗ Failed
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources 1 of 2 Working (4.7.1 (b) (i))
Advice	VSC light (Vehicle Stability Control light) illuminated
Advice	Front Run flat and conventional tyres mixed across the same axle.
Advice	Engine MIL: (malfunction indicator lamp) indicating a malfunction
Advice	Front Washers Working using Rear Washer Switch
Fail	Nearside Front Headlamp levelling device inoperative (4.1.5 (a))

**MOT #18** 2022-06-09 09:45**MOT test number** 761178810489**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Suspension component corroded but not seriously weakened all suspension arms (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17 2021-06-11 11:50**MOT test number** 988114105720**Result** ✓ Passed

- Advice** Surface corrosion on under side of vehicle

MOT #16 2021-06-11 11:20**MOT test number** 792465392236**Result** ✗ Failed

- Advice** Surface corrosion on under side of vehicle
- Fail** Headlamp aim too low (4.1.2 (a))

MOT #15 2020-08-13 10:13**MOT test number** 590466119544**Result** ✓ Passed

- Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing Sidewall damaged no cords exposed (5.2.3 (d) (ii))
- Advice** Items removed from driver's view prior to test
- Minor** Front Windscreen wiper blade defective Both slight smearing (3.4 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2019-08-23 16:18**MOT test number** 396984479845**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front under shield insecure**MOT #13** 2018-10-02 11:05**MOT test number** 912153419528**Result** ✓ Passed**Advice** Vehicle has lack of power causing slight smoke upon acceleration**MOT #12** 2018-02-19 11:41**MOT test number** 853163527499**Result** ✓ Passed**Advice** Offside Rear tyre has uneven wear**MOT #11** 2018-02-19 08:59**MOT test number** 735601509936**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear tyre has uneven wear**Advice** Front both tyres have heavy edge wear**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)

**MOT #10** 2016-12-20 12:13**MOT test number** 806622551476**Result** ✓ Passed**Advice** Nearside rear tyre worn on outer edge**Advice** Nearside front tyre worn on outer edge**MOT #9** 2015-12-18 13:20**MOT test number** 207952604496**Result** ✓ Passed**MOT #8** 2015-12-18 13:20**MOT test number** 125104259027**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2014-09-05 14:20**MOT test number** 477078744204**Result** ✓ Passed**Notice** N/S/F tyre has damage to outer sidewall**MOT #6** 2013-09-18 15:21**MOT test number** 396541963255**Result** ✓ Passed**MOT #5** 2012-09-11 14:06**MOT test number** 967455952239**Result** ✓ Passed**Notice** Front tyres wearing on inner edges.

**MOT #4** 2012-09-10 11:35**MOT test number** 717084652271**Result** ✗ Failed**Fail** Offside Headlamp aim too high (1.8)**Fail** Nearside Side repeater excessively damaged so that it is not visible from a reasonable distance (1.4.A.2e)**Fail** Nearside Headlamp aim too high (1.8)**Notice** Front tyres wearing on inner edges.**Fail** Nearside Side repeater has less than 50% of the light sources illuminating (1.4.A.2c)**MOT #3** 2011-09-14 11:25**MOT test number** 349697751443**Result** ✓ Passed**Notice** Slight wear to both front brake discs**MOT #2** 2011-09-14 11:25**MOT test number** 179897251272**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Slight wear to both front brake discs**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2010-08-31 11:01**MOT test number** 403033840276**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
10 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	10 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-26
Last registration	2023-06-08
Complete history	See info



Registration #1	2007-09-26	6 mi
Registration #2	2010-08-31	18.081 mi
Registration #3	2011-09-14	27.727 mi
Registration #4	2012-09-10	42.210 mi
Registration #5	2012-09-11	42.304 mi
Registration #6	2013-09-18	55.445 mi
Registration #7	2014-09-05	65.877 mi
Registration #8	2015-12-18	78.355 mi
Registration #9	2015-12-18	78.355 mi
Registration #10	2016-12-20	88.282 mi
Registration #11	2018-02-19	101.743 mi
Registration #12	2019-06-20	115.217 mi
Registration #13	2020-06-20	128.717 mi
Registration #14	2021-06-20	142.217 mi
Registration #15	2022-06-20	155.717 mi
Registration #16	2023-06-20	169.217 mi
Registration #17	2024-06-20	182.717 mi
Registration #18	2025-06-20	196.217 mi
Registration #19	2026-06-20	209.717 mi
Registration #20	2027-06-20	223.217 mi
Registration #21	2028-06-20	236.717 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1480 mm
Length	4645 mm
Wheel base	2700 mm
Kerb weight	1380 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4425233352