





report date: 2024-03-28

General information

Make	FIAT
Model	FIORINO 16V MULTIJET
Colour	White
Year of manufacture	2016
Top speed	97 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

	-	-	-	-	1
ᆮ	п	ıL	г١	,	1

ciitiy 1	
Date	2021-11-10
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-04
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	19
Total items failed	0

MOT #10	2024-04-05 11:21
MOT test number	177881840969
Result	✓ Passed
Next expiry date	2025-04-04

MOT #9	2024-01-11 13:47
MOT test number	235863265048
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8		2024-01-11 09:39
MOT test	number	669329743304
Result		× Failed
MAJOR	Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2023-01-12 16:31
MOT test	number 752930152682
Result	✓ Passed
Advice	Offside Rear Shock absorbers has a slightly worn bush upper/top mounting bush (5.3.2 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge at 2.5mm tread depth (5.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6 2022-01-20 09:16

MOT test number 630312793071

Result ✓ Passed

Advice Under bonnet and under vehicle inspections are limited because of covers.

MOT #5 2022-01-18 13:23

MOT test number 870121523054

Result X Failed

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Under bonnet and under vehicle inspections are limited because of covers.

MAJOR Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2021-04-27 10:11

MOT test number 112499467980

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-03-27 12:20

MOT test number 575163144941

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1

MOT test number

767210118032

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK NY
Plate since	
Current registration	NK NA
Plate since	
	More info

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-04-07
Last registration	2024-04-05
Complete history	See info



Registration #1	2016-04-07	17 mi
Registration #2	2019-04-02	20.069 mi
Registration #3	2019-04-02	20.069 mi
Registration #4	2020-03-27	27.578 mi
Registration #5	2021-04-27	37.198 mi
Registration #6		77,777 46
Registration #7		11.777 mi
Registration #8		71.777 es
Registration #9		11.777 mi
Registration #10		71.777 es
Registration #11		11.777 mi
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
50569	

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	5881317

CarCheck.co.uk page 12/12