





report date: 2024-03-28

General information

Make	RENAULT
Model	ZOE DYNAMIQUE INTENS
Colour	White
Year of manufacture	2014
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	87 BHP
Max. torque	220 Nm at 2.500 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 3

Date 2023-10-10

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2021-09-21

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-20
Pictures	0
Listing price	<u>View report</u>

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-03-30
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	21
Total items failed	4

MOT #9	2023-03-31 08:21
MOT test number	681874513964
Result	✓ Passed
Next expiry date	2024-03-30
Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i)) Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	

MOT #8	2023-03-29 14:25
MOT test number	197225482606
Result	X Failed
Fail Nearside Front Body component damaged and likely to cause injury door mirr	ror (6.2.1 (a) (i))
Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	
Fail Nearside Front Side repeater lens defective such that the emitted light is adversity)	ersely affected (4.4.1 (b)

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Frank

MOT test number

S31217821828

Result

Advice

Offside Rear Tyre slightly damaged/cracking or perishing 195/55/16 (5.2.3 (d) (ii))

Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing 195/55/16 (5.2.3 (d) (ii))

MOT #6		2021-05-12 11:49
MOT test	number	137813439131
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/13



Fail

Advice

Advice

GL64PPK

report date: 2024-03-28

MOT #5 2021-05-11 10:56 **MOT** test number 492633397356 Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #4

MOT test number

Result

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3

MOT test number

Result

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

 MOT #2
 2018-06-28 15:22

 MOT test number
 956411714608

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2017-12-13 10:33

MOT test number 554635233932

CarCheck.co.uk page 6/13



report date: 2024-03-28

30 March 2024

Tax & MOT check

MOT expiry date



Full MOT history See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



GL64PPK report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this RENAULT? How many own have? Check it in the premium report and see all owner registrations. Download the full	

THE STREET STREET, STR	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK NA
Plate since	
Current registration	ak (
Plate since	
	More info

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-12-16
Last registration	2023-03-31
Complete history	See info



Registration #1	2014-12-16	18 mi
Registration #2	2017-12-13	8.029 mi
Registration #3	2018-06-28	8.269 mi
Registration #4	2019-05-24	15.154 mi
Registration #5	2020-05-20	23.464 mi
Registration #6	2021-05-11	30.629 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 12/13



GL64PPK report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1943 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles Carcheck.co.uk	2 page 13/13