





report date: 2024-03-29

## General information

Make	CITROEN
Model	C4 PURETECH FLAIR S/S
Colour	White
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	100 g/km
CO2 label	A



CarCheck.co.uk page 1/12



# Internet history

#### Entry 1

Date	2021-01-29	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

**X** Failed

MOT history	M	OT	history
-------------	---	----	---------

MOT expiry date	2024-10-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	2

MOT #10	2023-10-03 07:19
MOT test number	174143826129
Result	✓ Passed
Next expiry date	2024-10-02

MOT #9	2023-03-02 16:37
MOT test number	570076409486
Result	<b>√</b> Passed

MOT #8	2023-03-01 11:18
MOT #8	2023-03-01 11:1

**MOT test number** 771358897148

Result

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**DANGEROUS** Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MAJOR** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

MOT #7	2022-03-10 16:53
MOT test number	602239822732
Result	<b>✓</b> Passed
Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #6 2021-08-13 15:15

**MOT test number** 895953623127

MOT #5 2021-08-05 11:26

**MOT test number** 312730809906

Result X Failed

**MAJOR** Offside Front Windscreen wiper not working (3.4 (a))

MAJOR Nearside Front Windscreen wiper not working (3.4 (a))

MOT #4 2021-03-08 11:48

**MOT test number** 273379956638

MOT #3 2020-06-05 07:31

**MOT test number** 446073139834

Result \( \sqrt{Passed} \)

Advice Parking brake lever defective but can be satisfactorily operated release button broken/missing

(1.1.6 (d))

CarCheck.co.uk page 4/12



report date: 2024-03-29

**MOT** #2 2020-05-30 08:40 402699562201 **MOT** test number Result × Failed **Advice** Fluid leak, but not excessive coolant(radiator area) (8.4.1 (a) (i)) **MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Minor Offside Windscreen wiper blade defective smears (3.4 (b) (i)) Pass with rectification Offside Headlamp aim too high (4.1.2 (a)) Coolant bottle below minimum Advice Advice Parking brake lever defective but can be satisfactorily operated release button broken/missing (1.1.6 (d))Pass with rectification Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))

MOT #1 2019-05-18 11:18

MOT test number 456952192876

Result ✓ Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	2 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

## Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



## Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	hictory
COMPLET	HISLOLV

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
PROFESSOR	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	NIP.
Flate since	
	More info >
	Piore inio /

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-05-31
Last registration	2023-10-03
Complete history	See info



Registration #1	2016-05-31	25 mi
Registration #2	2019-05-18	35.104 mi
Registration #3	2020-05-30	44.859 mi
Registration #4	2020-06-05	44.961 mi
Registration #5		11.777 es
Registration #6	2021-03-08	48.015 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1020 kg
Max. allowed weight	1555 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XV120205743

CarCheck.co.uk page 12/12